

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20014625/EBA3Q2
Date: 24/03/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SMK7057D	Insured Vehicle No :	SH6074E
Date of Loss:	23/12/2020	Nature of Claim:	TP
		Claim No:	MCT20120444

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK7057D		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11AG8567
Reg. Date:	22/04/2019 (Man. Year: 2018)	Chassis No:	GF7W0600937
Colour:	Grey	Odometer:	29425 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,486.00	3,189.00	2,297.00	41.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,690.00	1,290.00	43.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	8,466.00	4,879.00	3,587.00	42.37
+ GST 7.00/7.00% (\$\$)	592.62	341.53	251.09	42.37
Nett Amount (\$\$)	9,058.62	5,220.53	3,838.09	42.37
+ Car Rental (5.0 x S\$160.00/day + 7.00% GST) (\$\$)		856.00		
	Nett Liability (\$\$)	6,076.53		

INSPECTION

Date of Assignment:	28/12/2020	
Date Inspected:	11/01/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: CHUA ZHEN LI

3/24/2021

Adjuster Report

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Mar 2021)
Parts:	M1-SUV	MITSUBISHI OUTLANDER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK7057D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*HEADLAMP ASSY ,RH	Not Necessary	1,938.00 FS	*- FS
3	1		*FACE ,FR BUMPER	Dented	859.00 FS	*859.00 FS
4	1		*BRACKET ,FR BUMPER SIDE ,RH	Broken	18.00 FS	*18.00 FS
5	1		*EXTENSION ,FR BUMPER	Cut	515.00 FS	*515.00 FS
6	1		*GARNISH ,FR BUMPER SIDE	Broken	220.00 FS	*220.00 FS
7	1		*GARNISH ,FR BUMPER SIDE	Broken	112.00 FS	*112.00 FS
8	1		*GARNISH ,FR BUMPER SIDE	Not Necessary	48.00 FS	*- FS
9	1		*COVER ,FR BUMPER	Cut	359.00 FS	*359.00 FS
10	1		*GARNISH ,FR BUMPER ,RH	Cut	48.00 FS	*48.00 FS
11	1		*REINFORCEMENT ,FR BUMPER	Bent	490.00 FS	*490.00 FS
12	1		*REINF ,FR BUMPER SIDE ,RH	Not Necessary	69.00 FS	*- FS
13	1		*REINFORCEMENT ,FR BMPR SIDE	Not Necessary	22.00 FS	*- FS
14	1		*REINF ,FR BUMPER SIDE ,LH	Not Necessary	60.00 FS	*- FS
15	1		*BAR ,FR BUMPER GUARD	Not Necessary	130.00 FS	*- FS
16	1		*GRILLE ASSY ,RADIATOR	Cut	548.00 FS	*548.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	5,486.00	3,189.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRONT BUMPER & AFFECTED AREA	New	1,280.00	640.00
2	PAINT WORK ON FRONT BUMPER PANEL	New	1,100.00	550.00
3	PERFORM RUST PREVENTION	New	100.00	0.00
4	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	120.00	120.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	280.00	280.00
6	TO APPLY ZERTONA COATING ON AFFECTED AREA	New	100.00	100.00
Gross Labour Cost (S\$)			2,980.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >