

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20014627/T1EA3Q2
Date: 12/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800142574
Claimant Vehicle No :	SHB6635Z	Insured Vehicle No :	SKT1933R
Date of Loss:	26/12/2020	Nature of Claim:	TP
		Claim No:	9825926403SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB6635Z		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEKU296068
Reg. Date:	26/06/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU164415
Colour:	Blue	Odometer:	247647 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,931.72	4,967.84	4,963.88	49.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,730.00	1,210.00	41.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,871.72	6,697.84	6,173.88	47.96
+ GST 7.00/7.00% (S\$)	901.02	468.85	432.17	47.96

Nett Amount (S\$)	13,772.74	7,166.69	6,606.05	47.96
+ Loss of Use (8.5 x S\$50.00/day) (S\$)		425.00		
+ Car Rental (8.5 x S\$125.19/day) (S\$)		1,064.12		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,657.81		
Global Sum Settlement (S\$)		8,650.00		

INSPECTION

Date of Assignment: 28/12/2020

Date Inspected: 28/12/2020

Estimated Period of Repair: 4.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	2,480.40 FL	*2,480.40 FL
2	1		*BOOT LID RUBBER	Not Necessary	187.40 FL	*- FL
3	2		*BOOT LID HINGE (LH/RH)	Repair	71.30 FL	*- FL
4	1		*BOOT LID LOCK LOWER	Not Necessary	51.30 FL	*- FL
5	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
6	2		*BOOT LID ABSORBER (LH/RH)	Not Necessary	173.40 FL	*- FL
7	1		*EMBLEM -HYBRID	Necessary	24.30 FL	*24.30 FL
8	1		*EMBLEM -LONIQ	Necessary	31.30 FL	*31.30 FL
9	1		*ANTENNA ASSY -SMARTK	Cracked	40.50 FL	*40.50 FL
10	1		*BOOT LID GLASS ,UPPER	Not Necessary	907.20 FL	*- FL
11	1		*BOOT LID GLASS ,LOWER	Cracked	584.90 FL	*584.90 FL
12	2		*BOOT LID LAMP (LH/RH)	Not Necessary	1,588.80 FL	*- FL
13	1		*BOOT LID TRIMBOARD	Serviceable	259.70 FL	*- FL
14	2		*LICENCE LAMP (LH/RH)	Not Necessary	85.30 FL	*- FL
15	1		*BOOTLID GARNISH	Not Necessary	36.10 FL	*- FL
16	1		*BOOTLID LOWER GARNISH	Not Necessary	25.40 FL	*- FL
17	2		*TAIL LAMP ASSY LH/RH	Not Necessary	1,740.80 FL	*- FL
18	1		*REAR BUMPER	Deformed	459.40 FL	*459.40 FL
19	1		*REAR BUMPER REINFORCEMENT	Cracked	394.80 FL	*394.80 FL
20	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Bent	276.20 FL	*276.20 FL
21	1		*REAR BUMPER CENTRE MOULDING ASSY	Deformed	451.25 FL	*451.25 FL
22	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Repair	155.00 FL	*- FL
23	2		*REAR BUMPER SIDE BRACKET (LH/RH)	Not Necessary	111.60 FL	*- FL
24	10		*REAR BUMPER COVER CLIPS	Serviceable	22.00 FL	*- FL
25	1		*REAR BUMPER UNDER CENTRE COVER	Not Necessary	225.00 FL	*- FL
26	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Not Necessary	82.90 FL	*- FL
27	1		*REAR BUMPER FOG LAMP	Cracked	201.50 FL	*201.50 FL
28	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	*- FL
29	1		*REAR BUMPER LIP	Not Necessary	123.85 FL	*- FL
30	1		*REAR FOG LAMP	Repeated	201.50 FL	*- FL
31	1		*PANEL ASSY BACK	Bent	532.00 FL	*532.00 FL
32	1		*LATCH ASSY	Bent	224.00 FL	*224.00 FL
33	1		*BOOT LID COMFORT LOGO & TEL NO.STICKER	Necessary	60.00 FS	*60.00 FS
34	1		*BOOT LID APP LOGO STICKER	Necessary	40.00 FS	*40.00 FS
35	1		*REVERSE SENSOR	Not Working	180.00 FS	*180.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS
37	1		*REAR NO.PLATE W/HOLDER	Cracked	55.00 FS	*55.00 FS
38	1		*REAR WINDSCREEN SEALANT	Not Necessary	46.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,306.90	6,113.55
- List Item Discount on L Items 20.00/20.00% (\$)	2,375.18	1,145.71
Total Parts (\$)	9,931.72	4,967.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING CHARGE	New	1,000.00	600.00
3	WIRING CHARGE	New	90.00	30.00
4	TUFF KOTE	New	180.00	30.00
5	TOWING CHARGE	New	80.00	60.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	60.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (S\$)			2,940.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >