

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014628/KTD3Q2

Date: 05/02/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00051182000

Claimant Vehicle No : YP5592U **Insured Vehicle No :** SFN933M

Date of Loss: 24/12/2020 Nature of Claim: TP Claim No: SNM20D205096/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP5592U**
 Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (CBU) (M) Engine No: 4P10C40148
 Reg. Date: 24/02/2017 (Man. Year: 2016) Chassis No: FEB21EA21170
 Colour: Metallic Turquoise (Blue/Green) Odometer: 273473 km
 Engine Capacity: 2998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15 (D)
 Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 9/9 mm
 Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,217.06	5,043.21	2,173.85	30.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	1,510.00	400.00	20.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,127.06	6,553.21	2,573.85	28.20
Approved Total (Overridden) (S\$)		5,250.00		
(S\$)	9,127.06	5,250.00	3,877.06	42.48
+ GST 7.00/7.00% (S\$)	638.89	367.50	271.39	42.48
Nett Amount (S\$)	9,765.95	5,617.50	4,148.45	42.48

INSPECTION

Date of Assignment: 28/12/2020

Date Inspected: 29/12/2020 Inspected At:

Chew Goon Motor (AMK)
 Blk 10 Ang Mo Kio Industrial Park 2A,
 #01-15/16 & 17, AMK Autopoint
 Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Jan 2021)	
Parts:	N/A	mitsubishi CANTER 3.0 D FEB21ER3SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP5592U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,090.00 FN	*1,020.35 FN
2	1		*FRONT BUMPER BRACKET LH	Repair	211.64 FN	*- FN
3	1		*FRONT BUMPER COVER LH	Missing	368.50 FN	*322.37 FN
4	1		*FRONT BUMPER FOG LAMP COVER	Missing	104.00 FN	*104.00 FN
5	1		*HEADLAMP LH	Mtg Cracked	541.50 FN	*501.47 FN
6	1		*HEADLAMP LOWER RUBBER SEAL	Missing	15.06 FN	*15.06 FN
7	1		*HEADLAMP SIDE COVER LH	Missing	240.63 FN	*240.63 FN
8	1		*FRONT SIGNAL LAMP LH	Buckled	287.60 FN	*287.60 FN
9	1		*GRILLE	Mtg Cracked	1,194.00 FN	*1,105.63 FN
10	1		*GRILLE EMBLEM	Necessary	167.30 FN	*167.30 FN
11	1		*GRILLE BADGE CANTER	Necessary	89.10 FN	*89.10 FN
12	1		*FRONT CORNER PANEL LH	Mtg Cracked	346.00 FN	*346.00 FN
13	1		*FRONT DOOR LH	Bent	2,162.00 FN	*2,001.44 FN
14	1		*FRONT DOOR LOWER HINGE	Repair	175.50 FN	*- FN
15	1		*FRONT DOOR LOWER ARCH PROTECTOR	Repair	181.90 FN	*- FN
16	1		*FRONT DOOR LOWER STEP BOARD	Cut	310.00 FN	*310.00 FN
17	1		*FRONT PANEL BADGE FUSO	Not Necessary	112.00 FN	*- FN
18	1		*FRONT BUMPER STICKER	Necessary	30.00 FS	*30.00 FS
19	1		*GRILLE LED STRIPE LAMP	Necessary	150.00 FS	*80.00 FS
20	1		*FRONT DOOR STICKER	Necessary	80.00 FS	*50.00 FS
21	1		*FRONT PANEL CO LABEL	Non original	120.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	7,976.73	6,670.95
- Nett Item Discount on N Items 10.00/25.00% (\$\$)	759.67	1,627.74
Total Parts (\$\$)	7,217.06	5,043.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /TRANSFER DOOR FITTINGS /ANCILLAR ACCESSORIES	New	150.00	60.00
2	TO CONDUCT ELECTRICAL CHECK ,FOCUS HEADLAMP	New	30.00	20.00
3	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL	New	80.00	30.00
4	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF FRONT PANEL ,HEADLAMP PANEL ,FRONT DOOR PILLAR AND PARTS REPLACEMENT	New	650.00	500.00
5	TO RESPRAY AFFECTED AREAS	New	1,000.00	900.00
Gross Labour Cost (S\$)			1,910.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >