

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20014632/EVD3E2

Date: 01/02/2021

REFERENCE

Insured/Claimant:	SEAH JIE-WEI,SHAUN	Policy No:	2070134781		
Date of Loss:	28/12/2020	Nature of Claim:	OD	Claim No:	4502490870SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EB120S		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Engine No:	3A92UJP7568
Reg. Date:	22/09/2020 (Man. Year: 2020)	Chassis No:	MMBSTA13AMH000692
Colour:	Red	Odometer:	6396 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$64,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,618.50	3,629.05	989.45	21.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,840.00	2,365.00	1,475.00	38.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,458.50	5,994.05	2,464.45	29.14
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	8,158.50	5,694.05	2,464.45	30.21
+ GST 7.00/7.00% (S\$)	571.10	398.58	172.52	30.21
Nett Amount (S\$)	8,729.60	6,092.63	2,636.97	30.21

INSPECTION

Date of Assignment: 29/12/2020

Date Inspected: 29/12/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY,RH	Cut	1,697.00 FL	*1,697.00 FL
2	1		*LAMP ASSY,FOG,FR LH	Not Necessary	303.00 FL	*- FL
3	1		*FACE,FR BUMPER	Broken	703.00 FL	*703.00 FL
4	1		*GRILLE ASSY,RADIATOR	Cut	597.00 FL	*597.00 FL
5	1		*MARK,THREE-DIA	Necessary	53.00 FL	*53.00 FL
6	1		*GRILLE,FR UNDER	Broken	90.00 FL	*90.00 FL
7	1		*COVER,FR BUMPER GRILLE	Broken	157.00 FL	*157.00 FL
8	1		*GARNISH,FR BUMPER,RH	Missing	44.00 FL	*44.00 FL
9	1		*BRACKET,FR BUMPER SIDE,RH	Broken	8.00 FL	*8.00 FL
10	1		*GARNISH,FR BUMPER SIDE	Broken	120.00 FL	*120.00 FL
11	1		*GARNISH,FR BUMPER SIDE	Broken	168.00 FL	*168.00 FL
12	1		*AIR DAM,SIDE,FR RH	Not Necessary	19.00 FL	*- FL
13	1		*SHIELD,FR WHEELHOUSE RH	Not Necessary	98.00 FL	*- FL
14	1		*FENDER,FR RH	Repair	428.00 FL	*- FL
15	1		*TANK,WINDSHIELD WASHER	Crushed	74.00 FL	*74.00 FL
16	1		*CAP,WASHER TANK FILLER	Not Necessary	7.00 FL	*- FL
17	1		*MOTOR,WINDSHIELD WASHER	Not Necessary	139.00 FL	*- FL
18	1		*REINFORCEMENT,FR BUMPER	Not Necessary	291.00 FL	*- FL
19	1		*EMBLEM ECO	Necessary	17.00 FS	*17.00 FS
20	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
21	1		*COVER,FR BUMPER (Supplementary)	Crushed	12.00 FL	*12.00 FL
22	6		*RIVET,FR BUMPER (Supplementary)	Necessary	24.00 FL	*24.00 FL
23	1		*PANEL ASSY,FR END (Supplementary)	Dented	918.00 FL	*918.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,987.00	4,702.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,368.50	1,072.95
Total Parts (\$\$)	4,618.50	3,629.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER,FRT RH FENDER & AFFECTED AREA REPAIR ON SUPPORT PANEL	New	1,800.00	675.00
2	PAINT WORK ON FRT BUMPER,FRT RH FENDER & FRT SUPPORT PANEL	New	1,050.00	700.00
3	PERFORM RUST PREVENTION	New	40.00	40.00
4	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	REPLACE FRONT SUPPORT PANEL (Supplementary)	New	450.00	450.00
7	RESPRAY FRONT SUPPORT PANEL (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$\$)			3,840.00	2,365.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >