



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV16047/SEAH JIE-WEI, SHAUN (XIE JIEWEI) Reg No/Reg Date EB120S / 22/09/202 Date In/Mileage 28/12/2020/ 0 Chassis No MMBSTA13AMH000692 Engine No 3A92UJP7568 Make/Model MIT/21MY ATTRAGE 1.2 CVT (E31) Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	29/12/2020/ 09:38	QUK	282 / Kevin Leong	61249			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, FRT RH FENDER & AFFECTED AREA REPAIR ON SUPPORT PANEL					450 X 1.5			1800.00
E PNT98000 PAINT WORK ON FRT BUMPER, FRT RH FENDER & FRT SUPPORT PANEL					350 X 1			1050.00
M SUNDRY PERFORM RUST PREVENTION								40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY SUNDRIES								20.00
M HEADLAMP ASSY, RH					1.00	1697.00	23.00	1306.69
M LAMP ASSY, FOG, FR LH					1.00	303.00	23.00	233.31
M FACE, FR BUMPER					1.00	703.00	23.00	541.31
M GRILLE ASSY, RADIATOR					1.00	597.00	23.00	459.69
M MARK, THREE-DIA					1.00	53.00	23.00	40.81
M GRILLE, FR UNDER					1.00	90.00	23.00	69.30
M COVER, FR BUMPER GRILLE					1.00	157.00	23.00	120.89
M GARNISH, FR BUMPER, RH					1.00	44.00	23.00	33.88
M BRACKET, FR BUMPER SIDE, RH					1.00	8.00	23.00	6.16
M GARNISH, FR BUMPER SIDE					1.00	120.00	23.00	92.40
M GARNISH, FR BUMPER SIDE					1.00	168.00	23.00	129.36
M AIR DAM, SIDE, FR RH					1.00	19.00	23.00	14.63
M SHIELD, FR WHEELHOUSE, RH					1.00	98.00	23.00	75.46
M FENDER, FR RH					1.00	428.00	23.00	329.56
M TANK, WINDSHIELD WASHER					1.00	74.00	23.00	56.98
M CAP, WASHER TANK FILLER					1.00	7.00	23.00	5.39
M MOTOR, WINDSHIELD WASHER(*)					1.00	139.00	23.00	107.03
M REINFORCEMENT, FR BUMPER					1.00	291.00	23.00	224.07
M EMBLEM ECO					1.00	17.00	00.00	17.00

Estimate

Steve CLKK)
29/12/20, 11.00am
OO - Not Auth'd
EXCESS - ?
P/P
Ry BOL spj
4 days

CUT?
X NM
BR
CUT
nec
BR
(Top cover) - BR
? - MIS
- BR (chance)
- BR (chance)
? X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM
X NM

Estimate

Steve CLKK)

29/12/20, 11.00am

OO - N/A Authd

EXCESS - ?

P/P

Ry Bol spj

4 days

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamp

Nett	6,923.92
7% GST on	6923.92
Total Payable	7,408.59

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.