

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20014638/EQD3E2

Date: 26/01/2021

REFERENCE

Insured/Claimant:	MOHD ALI BIN MD ISMAIL	Policy No:	2100396312	
Date of Loss:	28/12/2020	Nature of Claim:	OD	Claim No: 9250702981SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ6657X	Engine No:	G4FGEH748588
Make & Model:	KIA FORTE K3, 1.6 (A)	Chassis No:	KNAFZ411MF5349018
Reg. Date:	18/12/2014 (Man. Year: 2014)	Odometer:	174557 km
Colour:	Brown		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$41,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45ZR17	Rear Tyre Size:	215/45ZR17
Front Left Side:	West Lake 4 mm	Rear Left Side:	West Lake 4 mm
Front Right Side:	West Lake 4 mm	Rear Right Side:	West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,493.60	2,252.80	1,240.80	35.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,590.00	1,350.00	1,240.00	47.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,083.60	3,602.80	2,480.80	40.78
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	5,483.60	3,002.80	2,480.80	45.24
+ GST 7.00/7.00% (S\$)	383.85	210.20	173.65	45.24
Nett Amount (S\$)	5,867.45	3,213.00	2,654.45	45.24

INSPECTION

Date of Assignment:	29/12/2020	
Date Inspected:	29/12/2020	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY-HEAD,LH	Cut	1,870.00 FL	*1,870.00 FL
2	1		*PANEL-FENDER,LH	Repair	435.00 FL	*- FL
3	1		*GUARD ASSY-FRONT WHEEL,LH	Torn	109.00 FL	*109.00 FL
4	1		*COVER-FR BUMPER	Broken	728.00 FL	*728.00 FL
5	1		*GRILLE ASSY-RADIATOR	Not Necessary	322.00 FL	*- FL
6	1		*MOULDING-FRONT BUMPER A/INTAKE	Not Necessary	104.00 FL	*- FL
7	1		*GRILLE-FRONT BUMPER SIDE,LH	Not Necessary	17.00 FL	*- FL
8	1		*LAMP ASSY-FRONT FOG,LH	Not Necessary	277.00 FL	*- FL
9	1		*ULTRASONIC SENSOR ASSY-FBWS	Not Necessary	187.00 FL	*- FL
10	1		*EXTN WIRING ASSY-SPAS	Not Necessary	128.00 FL	*- FL
11	1		*GARNISH-RADIATOR GRILLE,UPR	Not Necessary	48.00 FL	*- FL
12	1		*STRIP ASSY-FR BUMPER UPR	Not Necessary	33.00 FL	*- FL
13	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
14	1		*LOGO ASSY-KIA SUB (Supplementary)	Necessary	51.00 FL	*51.00 FL
15	1		*BRACKET-FR BUMPER SIDE MTG, LH (Supplementary)	Broken	13.00 FL	*13.00 FL
16	10		*CLIPS (Supplementary)	Necessary	20.00 FL	*20.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,362.00	2,811.00
- List Item Discount on L Items 20.00/20.00% (S\$)	868.40	558.20
Total Parts (S\$)	3,493.60	2,252.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER & LHF FENDER	New	1,600.00	400.00
2	RESPRAY FRT BUMPER & LHF FENDER	New	700.00	700.00
3	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCA PRO TEST USING HI-SCA PRO TEST	New	120.00	120.00
5	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
6	REMOVE & REFIT FRT PARKING ASSIST SENSOR	New	60.00	60.00
Gross Labour Cost (\$\$)			2,590.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >