



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Mohd Ali Bin Ismail Reg No/Reg Date SKQ6657X / 18/12/201 Date In/Mileage / 0 Chassis No KNAFZ411MF5349018 Engine No G4FGEH748588 Make/Model KIA/15MY F K3 1.6 A SX 690 BLACK Colour/Trim K3N / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	29/12/2020/ 11:02	QUE	261 / Edwin Caina	26458		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000		R	430 X 1				1600.00
RENEW FRT BUMPER & LHF FENDER							700.00
E PNT98000			350 X 2				30.00
RESPRAY FRT BUMPER & LHF FENDER							120.00
A 54900099							80.00
CHECK WIRING ELECREICAL SYSTEM & ADJUST HEADLAMP AIM							60.00
A 10028901							20.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							
APPLY ANTI CORROSION ON AFFECTED AREAS							
E PNT88000							
REMOVE & REFIT FRT PARKING ASSIST SENSOR							
M SUNDRY							
Sundries							
M LAMP ASSY-HEAD,LH		/ CUT	1.00	1870.00	20.00		1496.00
M PANEL-FENDER,LH		X R	1.00	435.00	20.00		348.00
M GUARD ASSY-FRONT WHEEL,LH		? / TN	1.00	109.00	20.00		87.20
M COVER-FR BUMPER		/ BR	1.00	728.00	20.00		582.40
M GRILLE ASSY-RADIATOR		X NM	1.00	322.00	20.00		257.60
M MOULDING-FRONT BUMPER A/INTAKE		X NM	1.00	104.00	20.00		83.20
M GRILLE-FRONT BUMPER SIDE,LH		? X NM	1.00	17.00	20.00		13.60
M LAMP ASSY-FRONT FOG,LH		? X NM	1.00	277.00	20.00		221.60
M ULTRASONIC SENSOR ASSY-FBWS		? X NM	1.00	187.00	20.00		149.60
M EXTN WIRING ASSY-SPAS		X NM	1.00	128.00	20.00		102.40
M GARNISH-RADIATOR GRILLE,UPR		X NM	1.00	48.00	20.00		38.40
M STRIP ASSY-FR BUMPER UPR		X NM	1.00	33.00	20.00		26.40

Estimate

* front bumper legs - ARE

Steve (CLKK) 29/12/20, 11:30am

SURVEYOR NAME:

Estimate

* First bump lays off

Steve (CLKK) 29/12/20, 11:30am

SURVEYOR NAME :

SURVEYOR SIGNATURE :

Confirm & accepted by

DATE :

REMARKS :

Nett 6,016.40
7% GST on 6016.40 421.15
Total Payable 6,437.55

KK Auto Consultants hence notify
the Repairer of the following:
To resurvey before/after spray painting
To display damaged part(s) during resurvey
Parts price are subject to confirmation
Third party survey is on a "Warranted Basis"

Authorized signatory and company stamp
Third party survey is on a "Warranted Basis"

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include
any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered
after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a
deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or
cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing
the rubber seal or other repair requiring the removal of the windscreen.