

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20014639/DVD3E2**Date:** 31/08/2021**REFERENCE**

Insured/Claimant: FIXWERKS PTE LTD Policy No: DMCVSNW00036162000

Date of Loss: 22/12/2020 Nature of Claim: OD Claim No: SNM20D204992/C01/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK3350M**
 Make & Model: PEUGEOT PARTNER, 1.5 (A) Engine No: 10Q3BP0008006
 Reg. Date: 19/05/2020 (Man. Year: 2019) Chassis No: VR3EFYHYCKJ640042
 Colour: Red Odometer: 16534 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: S\$62,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,086.60	8,539.60	547.00	6.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,400.00	2,440.00	2,960.00	54.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,486.60	10,979.60	3,507.00	24.21
- Excess (S\$)	450.00	450.00	0.00	0.00
(S\$)	14,036.60	10,529.60	3,507.00	24.98
+ GST 7.00/7.00% (S\$)	982.56	737.07	245.49	24.98
Nett Amount (S\$)	15,019.16	11,266.67	3,752.49	24.98

INSPECTION

Date of Assignment: 29/12/2020

Date Inspected: 29/12/2020 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
AutoPoint
Singapore 568047

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Aug 2021)	
Parts:	N/A	PEUGEOT PARTNER 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK3350M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Dented	885.00 F	*885.00 F
2	1		*BONNET LOCK (WCP)	Bent	75.00 F	*75.00 F
3	2		*BONNET HINGE LH & RH (WCP)	Bent	134.00 F	*134.00 F
4	1		*RADIATOR ASSY (WCP)	Bent / Punctured	435.00 F	*435.00 F
5	1		*A/C CONDENSOR ASSY (WCP)	Bent	350.00 F	*350.00 F
6	1		*RADIATOR FAN COMPLETE (WCP)	Broken	570.00 F	*570.00 F
7	1		*FRONT FENDER LH (WCP)	Bent / Dented	285.00 F	*285.00 F
8	1		*FRONT BUMPER REINFORCEMENT BAR (WCP)	Bent	525.00 F	*525.00 F
9	1		*FRONT GRILLE (WCP)	Cracked / Cut	840.00 F	*840.00 F
10	1		*FRONT GRILLE TOP COVER (WCP)	Cut / Broken	420.00 F	*420.00 F
11	1		*FRONT GRILLE CENTER PAD (WCP)	Broken	540.00 F	*540.00 F
12	1		*SET SPORT LAMP COVER LH & RH (WCP)	Not Necessary	120.00 F	*- F
13	1		*FRONT BUMPER GRILLE (WCP)	Broken	420.00 F	*420.00 F
14	1		*FRONT BUMPER BRACKET CENTER (WCP)	Broken	255.00 F	*255.00 F
15	1		*AIR CLEANER BOX (WCP)	Broken	285.00 F	*285.00 F
16	1		*FRONT TOP PANEL (WCP)	Cracked	37.00 F	*37.00 F
17	2		*FRONT SIDE PANEL LH & RH (WCP)	Bent / Dented	180.00 F	*180.00 F
18	1		*AIR CLEANER DEFLECTOR (WCP)	Deformed	75.00 F	*75.00 F
19	1		*RADIATOR HOSE (WCP)	Bent	25.00 F	*25.00 F
20	2		*HEAD LAMP LH & RH (WCP)	Mtg Broken	1,350.00 F	*1,350.00 F
21	1		*BONNET INNER TRIM CLIPS	Not fitted	50.00 FS	*- FS
22	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
23	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
24	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
25	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
26	1		*COOLANT	Not Necessary	100.00 FS	*- FS
27	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
28	1		*FRONT NO. PLATE & CASING	Broken	100.00 FS	*45.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$)	8,306.00	7,771.00
+ Margin on L,N Items 10.00/10.00% (\$)	780.60	768.60
Total Parts (\$)	9,086.60	8,539.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	1,200.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	1,000.00
3	TO TUFF COAT DAMAGED AREAS	New	300.00	30.00
4	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	80.00
5	TO RNR RADIATOR ASSY & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	50.00
6	TO RNR INTER-COOLER ASSY TO FACILITATE REPAIRS	New	200.00	50.00
7	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
8	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$)			5,400.00	2,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >