

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM20014647/Gqd3e2	
	8 SHENTON WAY TOWERSINGAPOR			Date:	06/01/2021	
	ATTN : YVONNE A	NG		Code:	ASM	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SJQ 3497Y	Veh. Inspected		FU 8075A	
	Policy No.	GA450360	Coverage (\$)		0.00	
	Claim No.	S0M02XPT	Excess (\$)		0.00	
	Assign From	YVONNE ANG	Assign Date		29/12/2020	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA RXZ	c.c		133	
	Engine No.	HIDDEN	Year of Reg.		2002	
	Chassis No.	ZMC264234	Colour		RED	
	Odometer	9912 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	80/80-18	DUNLOP		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	80/80-18	DUNLOP		4 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.					
5. General Information						
	Accident Date	23/11/2020	Inspect Date /	Time	29/12/2020 (04:30 PM)	
	Survey held at	25 Kaki Bukit Road 4, #06-28 Sy	nergy			
	Repairer TOH MOTOR ENTERPRISE					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
=	Estimate Days of Repair					
5b.		Estimate	Days of Repair			

Report Ref No. CS3/ASM20014647/Gqd3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor