

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20014648/UBA3Q2

Date:

19/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900115493

Claimant Vehicle No : SJC1198Y**Insured Vehicle No :**

SJU8131Z

Date of Loss: 22/12/2020

Nature of Claim:

TP

Claim No:

0769198775SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJC1198Y**

Make & Model: TOYOTA CAMRY, 2.0 ABS AIRBAG (A)

Engine No:

1AZE076376

Reg. Date: 31/01/2008 (Man. Year: 2007)

Chassis No:

MR053BK4107022045

Colour: Grey

Odometer:

352098 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,491.17	6,490.77	9,000.40	58.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,920.00	2,070.00	1,850.00	47.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,411.17	8,560.77	10,850.40	55.90
Approved Total (Overridden) (S\$)		6,900.00		

Nett Amount (S\$)	19,411.17	6,900.00	12,511.17	64.45
+ Loss of Use (8.0 x S\$120.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,867.45		
Global Sum Settlement (S\$)		7,700.00		

INSPECTION

Date of Assignment: 28/12/2020

Date Inspected: 29/12/2020

Estimated Period of Repair: 5.0 days

Inspected At:

Asia Motorsports Solution Pte Ltd (HQ)
 37A Everitt
 Singapore 428586

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Distorted	1,298.90 FL	*565.10 FL
2	1		*FRONT BUMPER LEFT RETAINER	Cracked	88.60 FL	*88.60 FL
3	1		*FRONT BUMPER LEFT BRACKET	Not Necessary	84.60 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	485.30 FL	*485.30 FL
5	1		*FRONT BUMPER TOW COVER	Not Necessary	87.60 FL	*- FL
6	1		*FRONT BUMPER SPONGE	Not Necessary	179.70 FL	*- FL
7	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	191.50 FL	*- FL
8	1		*FRONT SUPPORT PANEL	Bent / Dented	877.20 FL	*877.20 FL
9	1		*FRONT LEFT HID HEADLAMP	Broken	1,495.30 FL	*1,495.30 FL
10	1		*FRONT RIGHT HID HEADLAMP	Not Necessary	1,495.30 FL	*- FL
11	1		*FRONT LEFT HEADLAMP LOWER BRACKET	Not Necessary	88.70 FL	*- FL
12	1		*FRONT RIGHT HEADLAMP LOWER BRACKET	Not Necessary	88.70 FL	*- FL
13	1		*FRONT LEFT FOG LAMP	Cracked	280.10 FL	*280.10 FL
14	1		*FRONT LEFT FOG LAMP MOULDING	Cracked	122.20 FL	*122.20 FL
15	1		*FRONT LEFT FOG LAMP GARNISH	Missing	166.50 FL	*166.50 FL
16	1		*FRONT BONNET ASSY	Buckled	1,428.40 FL	*1,428.40 FL
17	1		*FRONT BONNET BRACE PANEL	Not Necessary	123.30 FL	*- FL
18	2		*FRONT HORN	Not Necessary	178.50 FL	*- FL
19	1		*FRONT LEFT FENDER	Buckled	1,512.20 FL	*671.10 FL
20	1		*FRONT LEFT FENDER VVTI EMBLEM	Necessary	67.20 FL	*52.50 FL
21	1		*FRONT LEFT FENDER INNER COWLING	Torn	116.30 FL	*116.30 FL
22	1		*FRONT GRILLE ASSY	Cracked	475.20 FL	*475.20 FL
23	1		*FRONT LEFT SUSPENSION ASSY	Not Necessary	767.40 FL	*- FL
24	1		*FRONT LEFT WHEEL HUB BEARING	Not Necessary	240.60 FL	*- FL
25	1		*FRONT LEFT LOWER ARM	Not Necessary	494.10 FL	*- FL
26	1		*FRONT LEFT KNUCKLE ARM	Not Necessary	561.60 FL	*- FL
27	1		*FRONT LEFT STABILIZER LINK	Not Necessary	121.50 FL	*- FL
28	1		*FRONT AIR CON CONDENSER ASSY	Serviceable	1,218.40 FL	*- FL
29	1		*FRONT AIR CON CONDENSER FAN COWLING	Not Necessary	393.90 FL	*- FL
30	1		*FRONT AIR CON CONDENSER FAN BLADE	Not Necessary	195.20 FL	*- FL
31	1		*FRONT AIR CON CONDENSER FAN MOTOR	Not Necessary	561.50 FL	*- FL
32	1		*FRONT RADIATOR ASSY	Holder Cracked	1,818.50 FL	*1,615.10 FL
33	1		*FRONT RADIATOR FAN COWLING	Not Necessary	384.70 FL	*- FL
34	1		*FRONT RADIATOR FAN BLADE	Not Necessary	163.50 FL	*- FL
35	1		*FRONT RADIATOR FAN MOTOR	Not Necessary	493.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	10		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
37	1		*FRONT LEFT WHEEL RIM	Not Necessary	950.00 FS	*- FS
38	1		*FRONT LEFT TYRE	Not Necessary	350.00 FS	*- FS
39	1		*FRONT AIR CON GAS	Not Necessary	80.00 FS	*- FS
40	2		*FRONT RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
41	1		*FRONT NO PLATE WITH GARNISH	Bent	100.00 FS	*40.00 FS
42	4		*FRONT LEFT FENDER INNER COWLING CLIPS	Necessary	20.00 FS	*20.00 FS
43	6		*FRONT BUMPER LOWER GRILLE ASSY	Not Necessary	30.00 FS	*- FS
44	4		*FRONT GRILLE CLIPS	Not Necessary	20.00 FS	*- FS
45	1		*FRONT GRILLE EMBLEM	Necessary	68.80 FL	*68.80 FL
					Sub Total (\$\$)	20,094.90
					- List Item Discount on L Items 25.00/25.00% (\$\$)	4,603.73
					Total Parts (\$\$)	15,491.17

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN FRONT AND FRONT LEFT AFFECTED AREA AND REPLACE FRONT AND FRONT LEFT DAMAGED PARTS	New	1,400.00	800.00
2	TO PUTTY AND SPRAY PAINTING FRONT AND FRONT LEFT PORTION	New	1,400.00	1,000.00
3	TO CHECK WIRING AND FOCUS FRONT HEADLAMP	New	50.00	30.00
4	TO REMOVE AND INSTALL AIR CON SYSTEM TO FACILITATE THE REPAIR AND REFILL GAS	New	150.00	100.00
5	TO REMOVE AND INSTALL COOLING SYSTEM TO FACILITATE THE REPAIR AND CHECK FOR LEAKAGE	New	150.00	0.00
6	TO APPLY ANTI RUST PROOFING TO FRONT AND FRONT LEFT AFFECTED AREA	New	150.00	90.00
7	TO REMOVE AND INSTALL FRONT LEFT UNDERCARRIAGE PARTS	New	350.00	0.00
8	TO BALANCE FRONT LEFT WHEEL	New	50.00	0.00
9	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
10	TOWING SERVICE	New	100.00	50.00
Gross Labour Cost (\$)			3,920.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >