

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

☐

Preli. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

5/1/21 1/3 @ 6900 Confirmed with AM long

Man: Jasper

Not Authorized
28/12/20
1/5 #6900
5 days. Take photo After repair

SJC1198Y Toyota Camry

			Estimated Parts Price
No	Qty	Parts Description	
1	1	Front bumper assy	\$ 1,298.90
2	1	Front bumper left retainer	\$ 88.60
3	1	Front bumper left bracket	\$ 84.60 X
4	1	Front bumper reinforcement	\$ 485.30
5	1	Front bumper tow cover	\$ 87.60 X
6	1	Front bumper sponge	\$ 179.70 X
7	1	Front bumper lower grille	\$ 191.50 X
8	1	Front support panel	\$ 877.20
9	1	Front left HID headlamp	\$ 1,495.30
10	1	Front right HID headlamp	\$ 1,495.30 X
11	1	Front left headlamp lower bracket	\$ 88.70 X
12	1	Front right headlamp lower bracket	\$ 88.70 X
13	1	Front left fog lamp	\$ 280.10
14	1	Front left fog lamp moulding	\$ 122.20
15	1	Front left fog lamp garnish	\$ 166.50
16	1	Front bonnet assy	\$ 1,428.40
17	1	Front bonnet brace panel	\$ 123.30 X
18	2	Front horn	\$ 178.50 X
19	1	Front left fender	\$ 1,512.20
20	1	Front left fender vvti emblem	\$ 67.20
21	1	Front left fender inner cowl	\$ 116.30
22	1	Front grille assy	\$ 475.20
23	1	Front grille emblem	\$ 68.80
24	1	Front left suspension assy	\$ 767.40 X
25	1	Front left wheel hub bearing	\$ 240.60 X
26	1	Front left lower arm	\$ 494.10 X
27	1	Front left knuckle arm	\$ 561.60 X
28	1	Front left stabilizer link	\$ 121.50 X
29	1	Front air con condenser assy	\$ 1,218.40 X
30	1	Front air con condenser fan cowl	\$ 393.90 X
31	1	Front air con condenser fan blade	\$ 195.20 X
32	1	Front air con condenser fan motor	\$ 561.50 X
33	1	Front radiator assy	\$ 1,818.50
34	1	Front radiator fan cowl	\$ 384.70 X
35	1	Front radiator fan blade	\$ 163.50 X
36	1	Front radiator fan motor	\$ 493.90 X
			\$ 18,114.90
			\$ 4,528.73
less 25%			\$ 13,586.18

8607.70
-25.2
6455.77

SJC1198Y Toyota Camry

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Front bumper clips <i>all</i>	\$ 50.00 ✓
2	1	Front left wheel rim <i>11</i>	\$ 950.00 X
3	1	Front left tyre <i>11</i>	\$ 350.00 X
4	1	Front air con gas <i>11</i>	\$ 80.00 X
5	2	Front radiator coolant <i>11</i>	\$ 80.00 X
6	1	Front no plate with garnish <i>Best</i>	\$ 100.00 <i>HO</i>
7	4	Front left fender inner cowlings clips <i>all</i>	\$ 20.00 ✓
8	6	Front bumper lower grille clips <i>11</i>	\$ 30.00 X
9	4	Front grille clips <i>11</i>	\$ 20.00 X
			\$ 1,680.00
Total parts			\$ 15,266.18

SJC1198Y Toyota Camry

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front and front left affected area and replace front and front left damaged parts.	\$ 1,400.00 800
2	To putty and spray painting front and front left portion.	\$ 1,400.00 1000
3	To check wiring and focus front headlamp.	\$ 50.00 30
4	To remove and install air con system to facilitate the repair and refill gas.	\$ 150.00 100
5	To remove and install cooling system to facilitate the repair and check for leakage.	\$ 150.00 X
6	To apply anti rust proofing to front and front left affected area.	\$ 150.00 90
7	To remove and install front left undercarriage parts.	\$ 350.00 X
8	To balance front left wheel.	\$ 50.00 X
9	To conduct wheel alignment.	\$ 20.00 X
10	Towing service.	\$ 100.00 50
Total labour :		\$ 3,920.00

Total parts : \$ 15,266.18

Total labour : \$ 3,920.00

Total repair cost : \$ 19,186.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-645577

S.N-110

L-2070

863577

6908