

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20014650/AVD3E2

Date: 08/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMV5130E

Insured Vehicle No : SJR4394Z

Date of Loss: 21/12/2020

Nature of Claim: TP

Claim No: 2270021289SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV5130E**

Make & Model: BMW 520I, 2.0 D/AB 2WD 4DR GAS/D NAV (A)

Engine No: B3590431N20B20B

Reg. Date: 28/03/2013 (Man. Year: 2013)

Chassis No: WBAXG12090DX53027

Colour: White

Odometer: 0 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Kumho 6 mm

Rear Left Side: Kumho 6 mm

Front Right Side: Kumho 6 mm

Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/12/2020

Date Inspected: 31/12/2020 Inspected At:

LUSH AUTOMOTIVE PTE LTD (HQ)
No. 8 Kaki Bukit Avenue 4,, #03-47 Premier@Kaki
Bukit,
Singapore 415875

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Repair	0.00 F	*- F
2	1		*ROCKER PANEL OUTER SIDE SKIRT LH	Repair	0.00 F	*- F
3	1		*REAR LH DOOR	Distorted	0.00 F	*- F
4	1		*REAR LH DOOR RUBBER	Necessary	0.00 F	*- F
5	1		*REAR BUMPER	Repair	0.00 F	*- F
6	1		*REAR LH FENDER	Dented	0.00 F	*- F
7	1		*REAR LH WHEEL RIM	Cut	0.00 F	*- F
8	1		*REAR LH SHOCK ABSORBER	Damaged	0.00 F	*- F
9	1		*REAR LH LOWER ARM	Damaged	0.00 F	*- F
10	1		*REAR LH STAY ARM	Damaged	0.00 F	*- F
11	1		*REAR LH KNUCKLE ARM	Damaged	0.00 F	*- F
12	1		*REAR LH WHEEL HUB	Damaged	0.00 F	*- F
13	1		*REAR LH WHEEL HUB BEARING	Damaged	0.00 F	*- F
14	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
15	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
F=Franchise part.						
					Total Parts (\$\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >