

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7348B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER REAR BUMPER	TORN	499.90	499.90
10	BUMPER PIECE	NECESSARY	22.00	22.00
1	RETAINER RR BUMPER	NOT NECESSARY	94.80	-
1	GUARD REAR BUMPER	CUT	552.60	552.60
	LESS 25% DISCOUNT		-292.33	-268.63
			876.97	805.87
	LABOUR			
	PANEL BEATING.		350.00	320.00
	SPRAYPAINT ON AFFECTED AREA.		250.00	200.00
	REMOVE/REFIX REVERSE SENSOR .		80.00	30.00
			680.00	550.00
	GRAND TOTAL		1,556.97	1,355.87
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,355.87

Report Ref No. NS/INC20014653/T1vd3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.