



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7385T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER REAR BUMPER	TORN	499.90	499.90
10	BUMPER PIECE	NECESSARY	22.00	22.00
1	RETAINER RR BUMPER	NOT NECESSARY	94.80	-
1	LENS & BODY RR LH UPPE	NOT NECESSARY	557.90	-
1	LENS & BODY RR COMB LH	NOT NECESSARY	548.40	-
	LESS 25% DISCOUNT		-430.75	-130.48
			1,292.25	391.42
	<u>LABOUR</u>			
	PANEL BEATING (REPAIR RR FENDER LH) .		500.00	320.00
	SPRAYPAINT ON AFFECTED AREA.		450.00	200.00
	CHECK ALL LIGHTING .		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	50.00	-
	REMOVE/REFIX REVERSE SENSOR .		80.00	30.00
			1,130.00	580.00
GRAND TOTAL			2,422.25	971.42
RECOMMENDED COST OF REPAIRS				971.42

Report Ref No. NS/INC20014654/T1qd3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.