

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315 Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2332T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER	TO REPAIR SEE LABOUR	418.30	-
1	RADIATOR GRILLE	CUT	1,409.10	1,409.10
1	FRT LICENSE PLATE BASE	DEFORMED	17.40	17.40
	LESS 20% DISCOUNT		-368.96	-285.30
			1,475.84	1,141.20
	NETT ITEMS			
1	NO PLATE (S) W/TRIM COVER (N)	CRACKED	55.00	55.00
	LESS 10% DISCOUNT		-5.50	-5.50
			49.50	49.50
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT BUMPER.		350.00	320.00
	SPRAYPAINT CHARGE.		250.00	200.00
			600.00	520.00
	GRAND TOTAL		2,125.34	1,710.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,350.00

Report Ref No. NS/INC20014655/T1td3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.