



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3222R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	I40V3 BUMPER W LIP & FOG	TORN	1,052.20	1,052.20
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	I40V2 COVER-FR FOG LAMP B	CUT	41.60	41.60
1	I40VC BRKT ASSY-FR BPR UP	NOT NECESSARY	44.80	-
1	I40VC BRACKET-FR BUMPER S	NOT NECESSARY	24.60	-
1	I40VC LAMP ASSY-HEAD LH	NOT NECESSARY	1,800.00	-
1	I40V3 GUARD ASSY-FRONT WH	TORN	174.90	174.90
1	I40VC CAP ASSY-WHEEL HUB	CUT	217.20	217.20
	LESS 20% DISCOUNT		-675.46	-301.58
			2,701.84	1,206.32
<u>SPECIAL NETT ITEMS</u>				
1	FRT FENDER ADVERTISEMENT LOGO LH (SN)	CUT	100.00	100.00
			100.00	100.00
<u>LABOUR</u>				
	PANEL BEATING.(REPAIR FRT FENDER LH).		600.00	420.00
	SPRAYPAINT ON AFFECTED AREA.		450.00	400.00
	CHECK ALL LIGHTING.		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	50.00	-
	ADJUST FRONT WHEEL ALIGNMENT.		80.00	80.00
			1,230.00	930.00
GRAND TOTAL			4,031.84	2,236.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,800.00

Report Ref No. NS/INC20014657/T1td3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.