



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3960T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	CRACKED	430.90	430.90
1	F/BUMPER UPR CTR MOULDING	CUT	368.50	368.50
1	F/BUMPER LWR CTR MOULDING	CUT	186.90	186.90
1	FRT BUMPER GRILLE LH	CUT	93.60	93.60
1	FRT BUMPER UPR BRKT LH	NOT NECESSARY	35.00	-
1	FRT BUMPER SIDE BRKT LH	CRACKED	28.00	28.00
1	HEADLAMP LH	CUT	1,993.65	1,993.65
1	FOGLAMP LH	CRACKED	642.50	642.50
1	RADIATOR GRILLE	NOT NECESSARY	1,409.10	-
1	FRT FENDER LH	TO REPAIR SEE LABOUR	588.80	-
1	FRT FENDER BLUE-DRIVE LH	NECESSARY	26.60	26.60
1	FRT FENDER SHIELD LH	TORN	164.70	164.70
	LESS 20% DISCOUNT		-1,193.65	-787.07
			4,774.60	3,148.28
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT FENDER LH.		700.00	480.00
	SPRAYPAINT CHARGE.		500.00	400.00
	CHECK ALL LIGHTING.		40.00	30.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	40.00	-
			1,280.00	910.00
GRAND TOTAL			6,054.60	4,058.28

RECOMMENDED COST OF REPAIRS (CONFIRMED)			4,058.28
--	--	--	-----------------

Report Ref No. NS/INC20014659/T1vd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.