

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20014663/UTD3Q2**Date:** 08/01/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00024172001

Claimant Vehicle No : GBH1444E **Insured Vehicle No :** SMF8907X

Date of Loss: 25/12/2020 Nature of Claim: TP Claim No: SNM20D205092/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH1444E**

Make & Model: NISSAN NV200, 1.5 (A) Engine No: K9KE628D422720

Reg. Date: 02/02/2018 (Man. Year: 2017) Chassis No: VSKYBAM20Z0156711

Colour: White Odometer: 111981 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70R14 Rear Tyre Size: 175/70R14

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,752.20	2,797.48	9,954.72	78.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,290.00	1,590.00	2,700.00	62.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,042.20	4,387.48	12,654.72	74.26
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	17,042.20	3,500.00	13,542.20	79.46

INSPECTION

Date of Assignment: 04/01/2021

Date Inspected: 29/12/2020 Inspected At: Asia Motorsports Solution Pte Ltd (HQ)
37A Everitt
Singapore 428586

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Jan 2021)	
Parts:	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH1444E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Dented/Deformed	1,250.00 FL	*632.00 FL
2	1		*REAR LEFT DOOR PANEL	Badly Dented	1,635.00 FL	*1,469.60 FL
3	1		*REAR RIGHT DOOR PANEL	Not Necessary	1,450.00 FL	*- FL
4	1		*REAR END LOWER PANEL	Badly Dented	1,650.00 FL	*212.40 FL
5	1		*REAR BUMPER LEFT RETAINER	Not Necessary	86.00 FL	*- FL
6	1		*REAR BUMPER RIGHT RETAINER	Not Necessary	86.00 FL	*- FL
7	2		*REAR BUMPER REFLECTOR	Not Necessary	66.00 FL	*- FL
8	1		*REAR BUMPER TOW COVER	Not Necessary	68.00 FL	*- FL
9	2		*REAR LEFT DOOR PANEL HINGES	Not Necessary	220.00 FL	*- FL
10	2		*REAR RIGHT DOOR PANEL HINGES	Not Necessary	220.00 FL	*- FL
11	1		*REAR LEFT TAILLAMP	Not Necessary	689.00 FL	*- FL
12	1		*REAR RIGHT TAILLAMP	Not Necessary	689.00 FL	*- FL
13	1		*REAR LEFT TAILLAMP WIRE HANRESS	Not Necessary	380.00 FL	*- FL
14	1		*REAR RIGHT TAILLAMP WIRE HANRESS	Not Necessary	380.00 FL	*- FL
15	1		*REAR TAILGATE LEFT LOCK MECHANISM (UPPER)	Not Necessary	295.00 FL	*- FL
16	1		*REAR TAILGATE RIGHT LOCK MECHANISM (UPPER)	Not Necessary	295.00 FL	*- FL
17	1		*REAR TAILGATE LEFT LOCK MECHANISM (LOWER)	Twisted/Jammed	288.00 FL	*135.20 FL
18	1		*REAR TAILGATE RIGHT LOCK MECHANISM (LOWER)	Not Necessary	288.00 FL	*- FL
19	1		*REAR LEFT DOOR CENTRE LOGO	Necessary	68.00 FL	*68.00 FL
20	1		*REAR LEFT DOOR WIPER MOTOR	Not Necessary	385.00 FL	*- FL
21	1		*REAR LEFT DOOR WIPER BLADE ASSY	Not Necessary	165.00 FL	*- FL
22	1		*REAR LEFT DOOR OUTER GARNISH	Not Necessary	181.00 FL	*- FL
23	1		*REAR EXHAUST PIPE	Not Necessary	1,650.00 FL	*- FL
24	1		*REAR TAILGATE LEFT LOCK CATCH (UPPER)	Not Necessary	95.00 FL	*- FL
25	1		*REAR TAILGATE RIGHT LOCK CATCH (UPPER)	Not Necessary	95.00 FL	*- FL
26	1		*REAR TAILGATE LEFT LOCK CATCH (LOWER)	Not Necessary	88.00 FL	*- FL
27	1		*REAR TAILGATE RIGHT LOCK CATCH (LOWER)	Not Necessary	88.00 FL	*- FL
28	1		*REAR END LOWER PANEL TOP GARNISH	Not Necessary	128.00 FL	*- FL
29	1		*REAR TAILGATE WEATHERSTRIP	Twisted	280.00 FL	*280.00 FL
30	12		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
31	1		*REAR LEFT DOOR 70KM/H STICKER	Necessary	50.00 FS	*10.00 FS
32	1		*REAR LEFT DOOR GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
33	1		*REAR RIGHT DOOR GLASS SEALANT	Not Necessary	80.00 FS	*- FS
34	4		*REAR LEFT DOOR OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
35	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
36	1		*REAR NO PLATE WITH GARNISH	Not Necessary	100.00 FS	*- FS
37	1		*REAR END LOWER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
38	4		*REAR END LOWER PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (\$)	14,078.00	3,077.20
					- List Item Discount on L Items 10.00/10.00% (\$)	1,325.80	279.72
					Total Parts (\$)	12,752.20	2,797.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,400.00	600.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,400.00	680.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	20.00
4	TO REMOVE AND INSTALL BOTH REAR DOOR LOCK MECHANISM }	New	140.00	80.00
5	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR }	New	180.00	0.00
6	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	140.00	60.00
7	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	50.00
8	TO REMOVE AND INSTALL BOTH REAR DOOR GLASS TO FACILITATE THE REPAIR	New	250.00	100.00
9	TO CHECK ALL DOOR CENTRE LOCKING FOR FUNCTION	New	80.00	0.00
10	TO REPAIR,STRAIGHTEN AND ALIGN BOTH REAR FENDER PANEL	New	350.00	0.00
11	TO REMOVE AND INSTALL REAR EXHAUST PIPE ASSY	New	120.00	0.00
12	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (\$\$)			4,290.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >