



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 4052R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	880.00	-
10	FRONT BUMPER CLIPS @\$5.00 (CONSISTENT)	SERVICEABLE	50.00	-
1	FRONT BUMPER RETAINER RH (CONSISTENT)	SERVICEABLE	30.00	-
1	FRONT BUMPER RETAINER LH (CONSISTENT)	SERVICEABLE	30.00	-
1	FRONT REINFORCEMENT (CONSISTENT)	SERVICEABLE	380.00	-
1	REAR BUMPER (CONSISTENT)	CRUMPLED	880.00	880.00
10	REAR BUMPER CLIP @\$5.00 (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR BUMPER RETAINER RH (CONSISTENT)	SERVICEABLE	30.00	-
1	REAR BUMPER RETAINER LH (CONSISTENT)	SERVICEABLE	30.00	-
1	REAR UNDERCOVER COVER (CONSISTENT)	SERVICEABLE	280.00	-
1	REAR TAILGATE DOOR (CONSISTENT)	DENTED	1,080.00	1,080.00
1	REAR TAILGATE DOOR LOCK (CONSISTENT)	JAMMED	280.00	280.00
1	REAR TAILGATE DOOR LOCK LATCH (CONSISTENT)	SERVICEABLE	50.00	-
1	REAR TAILGATE DOOR RUBBER SEAL (CONSISTENT)	SERVICEABLE	120.00	-
1	REAR VEZEL EMBLEM (CONSISTENT)	NECESSARY	80.00	80.00
1	REAR HONDA EMBLEM (CONSISTENT)	SERVICEABLE	80.00	-
1	REAR /END PANEL GARNISH (CONSISTENT)	SERVICEABLE	200.00	-
1	END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	480.00	-
1	REAR WINDSCREEN MOLDING (CONSISTENT)	NECESSARY	100.00	100.00
	LESS 20% DISCOUNT		-	-494.00
			5,110.00	1,976.00
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT LICENSE PLATE WITH FRAME (SN) (CONSISTENT)	SERVICEABLE	40.00	-
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	200.00	200.00
			280.00	240.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	SPRAY PAINTING FRONT BUMPER AND WHOLE REAR INCLUDE BLENDING .		1,000.00	600.00
	REPLACE REAR INCLUDING FITTING,CUT ,WELD AND RE-ALIGN .INCLUSIVE OF THE REPAIR OF END PANEL AND FRONT BUMPER.		1,200.00	600.00
	REMOVE AND REFIT REAR BUMPER REVERSE SENSOR .		80.00	30.00
	TRANSFER DOOR FITTING AND WINDOW MECHANISM TO NEW DOOR .		80.00	50.00
	REMOVE AND REFIT REAR WINDSCREEN .		120.00	120.00
	APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL.		100.00	40.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
			2,610.00	1,470.00
	GRAND TOTAL		8,000.00	3,686.00
RECOMMENDED COST OF REPAIRS				3,686.00

Report Ref No. CC4/ASM20014682/Qga3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.