



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2101705

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 17/03/2021
Reference CC4/FCI20014686/Kea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SKZ 4483X
Insured Veh. SHB 2213J
Claim No. D21000027MFSH/1
Policy No. D-20094921MFSH
Accident Date 27/12/2020
Inspection Date 04/01/2021

Description	Total
Survey Inspection	205.00
Digital Photographs	
Transportation	
Subtotal	205.00
GST (7%)	14.35
Grand Total	219.35

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20014686/Kea3q2	
			Date: 17/03/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2213J	Veh. Inspected	SKZ 4483X	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D21000027MFSH/1	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	29/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	NHP1707008703	Colour	METALLIC BROWN	
Odometer	82889 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/50 R16	YOKOHAMA	8 mm	
L/H Front Tyre	205/50 R16	YOKOHAMA	8 mm	
R/H Rear Tyre	205/50 R16	YOKOHAMA	8 mm	
L/H Rear Tyre	205/50 R16	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/12/2020	Inspection Date	04/01/2021	
Survey held at	BODYFIX NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 4483X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEAD LAMP (LH)	CUT	1,812.45	1,812.45
1	HEAD LAMP BRACKET (LH)	TO REPAIR SEE LABOUR	182.00	-
1	FRONT FENDER (LH)	BENT	681.90	654.40
1	FRONT FENDER INNER SHIELD (LH)	DISTORTED	271.45	225.00
1	FRONT BUMPER	BUCKLED / DISTORTED	581.90	581.90
8	FRONT BUMPER CLIPS @\$3.50	NECESSARY	28.00	28.00
1	FRONT BUMPER SIDE RETAINER -LH	DISTORTED	178.85	178.85
1	EMBLEM 'HYBRID'	NECESSARY	89.20	89.20
1	FOG LAMP COVER LH	SCRATCHED	192.60	192.60
	LESS 25% DISCOUNT		-	-940.60
			4,018.35	2,821.80
	<u>LABOUR</u>			
	LABOUR TO REPLACE ABOVE PARTS ,PANEL BEAT ,REPAIR & RE-ALIGN DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF HEAD LAMP BRACKET (LH).		1,000.00	400.00
	SPRAY PAINT LH FRONT FENDER ,FRONT BUMPER & OTHER AFFECTED AREAS.		900.00	440.00
			1,900.00	840.00
	GRAND TOTAL		5,918.35	3,661.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,900.00

Report Ref No. CC4/FCI20014686/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKZ 4483X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

