

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20014687/DGA3Q2

Date: 30/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100413189

Claimant
Vehicle No : SMG542L **Insured Vehicle No :** SGD666A

Date of Loss: 24/12/2020 Nature of Claim: TP Claim No: 5402352013SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG542L		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK064668
Reg. Date:	30/11/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF58JA112896
Colour:	Red	Odometer:	45409 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,250.10	8,871.10	18,379.00	67.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,950.00	1,020.00	3,930.00	79.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,200.10	9,891.10	22,309.00	69.28
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	32,200.10	7,500.00	24,700.10	76.71
+ GST 7.00/7.00% (S\$)	2,254.01	525.00	1,729.01	76.71
Nett Amount (S\$)	34,454.11	8,025.00	26,429.11	76.71
+ Car Rental (6.0 x S\$160.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		1,284.00		
Nett Liability (S\$)		10,305.45		
Global Sum Settlement (S\$)		10,300.00		

INSPECTION

Date of Assignment: 28/12/2020

Date Inspected: 30/12/2020 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP LH	Mtg Broken	5,980.00 FL	*5,980.00 FL
2	1		*HEAD LAMP LOWER BRACKET LH	Not Necessary	240.00 FL	*- FL
3	1		*HEAD LAMP PANEL LH	Not Necessary	699.00 FL	*- FL
4	1		*BONNET	Not Necessary	2,531.00 FL	*- FL
5	1		*FRONT BUMPER	Cut / Mtg Broken	2,980.00 FL	*2,251.00 FL
6	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	420.00 FL	*- FL
7	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	120.00 FL	*- FL
8	1		*FRONT BUMPER FOG LAMP GARNISH LH	Not Necessary	274.00 FL	*- FL
9	2		*FRONT BUMPER SENSOR	Not Necessary	700.00 FL	*- FL
10	4		*FRONT BUMPER SENSOR HOLDER	Not Necessary	80.00 FL	*- FL
11	4		*FRONT BUMPER SENSOR O-RING	Not Necessary	40.00 FL	*- FL
12	1		*FRONT BUMPER SENSOR WIRE HARNESS	Not Necessary	2,140.00 FL	*- FL
13	1		*FRONT BUMPER UNDER COVER	Not Necessary	410.00 FL	*- FL
14	1		*FRONT FENDER LH	Dented	2,339.00 FL	*1,048.00 FL
15	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	195.00 FL	*- FL
16	1		*FRONT WHEEL BEARING LH	Not Necessary	482.00 FL	*- FL
17	1		*FRONT WHEEL BEARING HUB LH	Not Necessary	522.00 FL	*- FL
18	1		*FRONT KNUCKLE ARM LH	Not Necessary	824.00 FL	*- FL
19	1		*FRONT LOWER ARM LH	Not Necessary	492.00 FL	*- FL
20	1		*FRONT ABSORBER LH	Not Necessary	1,140.00 FL	*- FL
21	1		*FRONT STABILIZER BAR	Not Necessary	398.00 FL	*- FL
22	1		*FRONT STABILIZER LINK	Not Necessary	284.00 FL	*- FL
23	1		*FRONT UPPER ARM LH	Not Necessary	599.00 FL	*- FL
24	1		*BONNET INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
25	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
26	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
27	1		*FRONT BUMPER FOGL AMP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
28	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*FRONT RIM LH	Not Necessary	2,000.00 FS	*- FS
30	1		*TYRE	Not Necessary	500.00 FS	*- FS
31	1		*PAINT PROTECTION FILM FOR FENDER ,BUMPER BONNET	Necessary	3,000.00 FS	*500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 29,639.00 9,799.00
- List Item Discount on L Items 10.00/10.00% (\$\$) 2,388.90 927.90

Total Parts (\$\$) 27,250.10 8,871.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,800.00	400.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,800.00	400.00
3	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
4	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	0.00
5	TO RNR FRONT BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	40.00
6	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
7	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
Gross Labour Cost (\$\$)			4,950.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >