

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SGD666A [YOUR INSURED] & SMG542L [OUR CLIENT]
ON 24/12/2020.

ESTIMATED REPAIR COSTS FOR SMG542L

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	HEAD LAMP LH <i>monday broken</i>	\$ 5,980.00	✓
1PC	HEAD LAMP LOWER BRACKET LH <i>HL</i>	\$ 240.00	X
1PC	HEAD LAMP PANEL LH <i>HL</i>	\$ 699.00	X
1PC	BONNET <i>HL</i>	\$ 2,531.00	X
1PC	FRONT BUMPER <i>cut monday broken</i> 2251.00	\$ 2,980.00	✓
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$210.00 EACH <i>HL</i>	\$ 420.00	X
1PC	FRONT BUMPER TOW HOOK COVER <i>HL</i>	\$ 120.00	X
1PC	FRONT BUMPER FOG LAMP GARNISH LH <i>HL</i>	\$ 274.00	X
2PCS	FRONT BUMPER SENSOR @ \$350.00 EACH <i>HL</i>	\$ 700.00	X
4PCS	FRONT BUMPER SENSOR HOLDER @ \$20.00 EACH <i>HL</i>	\$ 80.00	X
4PCS	FRONT BUMPER SENSOR O-RING @ \$10.00 EACH <i>HL</i>	\$ 40.00	X
1PC	FRONT BUMPER SENSOR WIRE HARNESS <i>HL</i>	\$ 2,140.00	X
1PC	FRONT BUMPER UNDERCOVER <i>HL</i>	\$ 410.00	X
1PC	FRONT FENDER LH <i>Dent</i> 1048.00	\$ 2,339.00	✓
1PC	FRONT FENDER INNER SHIELD LH <i>HL</i>	\$ 195.00	X
1PC	FRONT WHEEL BEARING LH <i>HL</i>	\$ 482.00	X
1PC	FRONT WHEEL BEARING HUB LH <i>HL</i>	\$ 522.00	X
1PC	FRONT KNUCKLE ARM LH <i>HL</i>	\$ 824.00	X
1PC	FRONT LOWER ARM LH <i>HL</i>	\$ 492.00	X
1PC	FRONT ABSORBER LH <i>HL</i>	\$ 1,140.00	X
1PC	FRONT STABILIZER BAR <i>HL</i>	\$ 398.00	X
1PC	FRONT STABILIZER LINK <i>HL</i>	\$ 284.00	X
1PC	FRONT UPPER ARM LH <i>HL</i>	\$ 599.00	X

PARTS SUM: \$ 23,889.00

PARTS LESS 10%: \$ 2,388.90

PARTS TOTAL: \$ 21,500.10

9279.00
8351.10

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY BONNET INNER TRIM CLIPS <i>HL</i>	\$ 50.00	X
*	TO SUPPLY HEAD LAMP CLIPS <i>HL</i>	\$ 50.00	X
*	TO SUPPLY FRONT BUMPER CLIPS <i>HL</i>	\$ 50.00	20/-
*	TO SUPPLY FRONT BUMPER FOGL AMP GARNISH CLIPS <i>HL</i>	\$ 50.00	X
*	TO SUPPLY FRONT BUMPER UNDER COVER CLIPS <i>HL</i>	\$ 50.00	X
*	TO SUPPLY FRONT RIM LH <i>HL</i>	\$ 2,000.00	X
*	TO SUPPLY 1PC TYRE <i>HL</i>	\$ 500.00	X
*	TO SUPPLY PAINT PROTECTION FILM FOR FENDER, BUMPER & <i>HL</i> BONNET X <i>provide 64 receipt.</i> <i>500.00</i>	\$ 3,000.00	2,500/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 1,800.00	400/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 1,800.00	400/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00	HL
*	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 400.00	HL
*	TO RNR FRONT BUMPER SENSOR TO FACILITATE REPAIRS	\$ 150.00	40/-
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	30/-
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00	150/-

LABOUR & S/N TOTAL: \$ 10,700.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 32,200.10

30/12/2020 c 1700hrs

HLA Autum

1/2 hr 4 days.

1 year

2kk Auto

Check part prices.

9891.10

4/5 7500/-

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: