



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GK3-3419536

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT LID	BADLY DENTED	955.00	845.20
1	REAR BOOT LID HONDA LOGO	NOT NECESSARY	85.00	-
1	REAR BOOT LID FIT LOGO	NECESSARY	45.00	45.00
1	REAR BUMPER	DEFORMED	790.80	492.70
1	SET REAR BUMPER CLIP	NECESSARY	52.00	35.00
1	REAR BUMPER REVERSE SENSOR	SERVICEABLE	380.00	-
2	REAR BUMPER SIDE RETAINER @\$85.00	O/S BENT	170.00	17.30
1	REAR R/H TAIL LAMP	SCRATCHED	527.40	325.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	390.60	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	90.80	-
	LESS 20% DISCOUNT		-	-352.04
			3,486.60	1,408.16
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
			50.00	40.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT TRIMBOARD.		180.00	60.00
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	50.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	TO CHECK WIRING.		100.00	20.00
	TUFF KOTE.		150.00	30.00
	TOWING.		120.00	100.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	520.00
	SPRAY PAINTING.		800.00	600.00
			2,370.00	1,500.00
	GRAND TOTAL		5,906.60	2,948.16

Report Ref No. CS/SMO20014690/Uqd3e2



RECOMMENDED COST OF REPAIRS			2,948.16
-----------------------------	--	--	-----------------

Report Ref No. CS/SMO20014690/Uqd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.