

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20014691/T1EA3Q2**Date:** 07/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700006961
Claimant Vehicle No :	SJV9493S	Insured Vehicle No :	SJH6608Y
Date of Loss:	19/12/2020	Nature of Claim:	TP
		Claim No:	0618696764SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV9493S	Engine No:	B4450673N20B20B
Make & Model:	BMW 520I, 2.0 AT D/AB 2WD 4DR LED NAV (A)	Chassis No:	WBA5A32010D335162
Reg. Date:	29/07/2014 (Man. Year: 2013)	Odometer:	68114 km
Colour:	Silver		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,863.15	9,017.19	4,845.96	34.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	1,260.00	3,640.00	74.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,763.15	10,277.19	8,485.96	45.23
Approved Total (Overridden) (S\$)		8,250.00		
(S\$)	18,763.15	8,250.00	10,513.15	56.03
+ GST 7.00/7.00% (S\$)	1,313.42	577.50	735.92	56.03
Nett Amount (S\$)	20,076.57	8,827.50	11,249.07	56.03
+ Car Rental (5.0 x S\$130.00/day) (S\$)		650.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,484.95		
Global Sum Settlement (S\$)		9,480.00		

INSPECTION

Date of Assignment:	29/12/2020		
Date Inspected:	29/12/2020	Inspected At:	AP Automotive Services Pte Ltd (HQ) Blk 9006 Tampines Street 93, #01-202 Singapore 528840
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Cut	4,224.75 FL	*4,224.75 FL
2	1		*HEADLAMP BALLAST RH	Not Necessary	893.90 FL	*- FL
3	1		*HEADLAMP LOWER BRACKET RH	Cracked	321.00 FL	*321.00 FL
4	1		*HEADLAMP NOZZLE RH	Not Necessary	309.00 FL	*- FL
5	1		*FRONT BUMPER	Deformed	1,621.40 FL	*1,621.40 FL
6	1		*FRONT BUMPER LOGO -BMW	Necessary	110.00 FL	*110.00 FL
7	2		*FRONT BUMPER GRILLE L+R	Not Necessary	270.30 FL	*- FL
8	2		*FRONT BUMPER GRILLE CHROME FRAME L+R		0.00 FL	*- FL
9	2		*FRONT BUMPER GRILLE INNER BRACKET L+R	Not Necessary	86.90 FL	*- FL
10	1		*FRONT BUMPER GRILLE FAN	Not Necessary	401.75 FL	*- FL
11	1		*FRONT BUMPER GRILLE FAN MOTOR		0.00 FL	*- FL
12	1		*FRONT BUMPER NOZZLE COVER RH	Not Necessary	85.00 FL	*- FL
13	1		*FRONT BUMPER NOZZLE COVER LEVER RH	Not Necessary	162.00 FL	*- FL
14	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	374.00 FL	*- FL
15	1		*FRONT BUMPER TOW COVER RH	Not Necessary	374.00 FL	*- FL
16	1		*FRONT BUMPER FOGLAMP RH	Cut	311.00 FL	*311.00 FL
17	1		*FRONT BUMPER FOGLAMP GRILL RH	Cut	179.00 FL	*179.00 FL
18	1		*FRONT BUMPER FOGLAMP GRILL GARNISH RH	Cut	186.00 FL	*186.00 FL
19	1		*SET FRONT BUMPER SENSOR	Cut	1,060.00 FL	*1,060.00 FL
20	1		*FRONT BUMPER RETAINER RH	Cracked	101.00 FL	*101.00 FL
21	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	795.00 FL	*- FL
22	1		*FRONT BUMPER SPONGE	Cut	170.00 FL	*170.00 FL
23	1		*FRONT BUMPER UNDERCOVER	Not Necessary	249.00 FL	*- FL
24	1		*FRONT FENDER RH	Bent	974.00 FL	*974.00 FL
25	1		*FRONT BUMPER COWLING RH	Cut	181.00 FL	*181.00 FL
26	1		*FRONT SUPPORT PANEL	Not Necessary	634.00 FL	*- FL
27	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	203.00 FL	*- FL
28	10		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
29	10		*FRONT FENDER COWLING CLIPS	Necessary	100.00 FS	*20.00 FS
30	10		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,577.00	9,489.15
- List Item Discount on L Items 5.00/5.00% (\$\$)	713.85	471.96
Total Parts (\$\$)	13,863.15	9,017.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON AFFECTED AREAS	New	1,250.00	500.00
2	PANEL BEATING ON AFFECTED AREAS	New	800.00	500.00
3	TO CHECK WIRING AND HEADLAMP FOCUS }	New	150.00	50.00
4	TO CHECK WIRING AND FOG LAMP FUNCTION }	New	150.00	0.00
5	TO UNLOAD AND RNR UPHOLSTERY	New	400.00	0.00
6	TO CHECK WATER LEAK	New	150.00	0.00
7	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	1,200.00	150.00
8	TO PERFORM RUST PROOFING	New	400.00	30.00
9	TO RNR FRONT SENSOR AND CHECK FUNCTION	New	400.00	30.00
Gross Labour Cost (\$)			4,900.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >