

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III20014695/UVD3Q2

Date: 14/01/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant
Vehicle No : SKJ7688L

Insured Vehicle No : SHD6645J

Date of Loss: 24/12/2020

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKJ7688L**

Make & Model: MERCEDES-BENZ C180K, 1.6 (A)

Engine No: 27191031258160

Reg. Date: 19/10/2009 (Man. Year: 2009)

Chassis No: WDD2040452A316916

Colour: Grey

Odometer: 172240 km

Engine Capacity: 1597 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18

Rear Tyre Size: 225/40R18

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,998.00	4,721.76	11,276.24	70.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,000.00	1,330.00	4,670.00	77.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	21,998.00	6,051.76	15,946.24	72.49
Approved Total (Overridden) (\$)		4,800.00		
(S\$)	21,998.00	4,800.00	17,198.00	78.18
+ GST 7.00/7.00% (S\$)	1,539.86	336.00	1,203.86	78.18
Nett Amount (S\$)	23,537.86	5,136.00	18,401.86	78.18

INSPECTION

Date of Assignment: 29/12/2020

Date Inspected: 05/01/2021 Inspected At:

Kaizen Motors Pte Ltd (HQ)
68 KAKI BUKIT AVE 6, #02-12 ARK
@ KAKI BUKIT
Singapore 417896

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jan 2021)
Parts:	143	MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKJ7688L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT L/H DOOR	Badly Dented	2,450.00 F	*2,450.00 FL
2	1	*FRONT L/H DOOR SEAL	Not Necessary	475.00 F	*- FL
3	2	*FRONT L/H DOOR PLUG	Not Necessary	32.00 F	*- FL
4	2	*FRONT L/H DOOR HINGES	Not Necessary	390.00 F	*- FL
5	1	*FRONT L/H DOOR HINGE COVER CAP	Not Necessary	15.00 F	*- FL
6	1	*FRONT L/H DOOR SEALING	Not Necessary	52.00 F	*- FL
7	1	*FRONT L/H DOOR B PILLAR TRIM	Not Necessary	200.00 F	*- FL
8	1	*FRONT L/H STRIP RUBBER	Necessary	58.00 F	*58.00 FL
9	3	*FRONT L/H DOOR REINFORCEMENT	No such part	165.00 F	*- FL
10	1	*FRONT L/H DOOR DAMPENER	Not Necessary	70.00 F	*- FL
11	1	*FRONT L/H DOOR HANDLE W CHROME	Not Necessary	780.00 F	*- FL
12	1	*FRONT L/H POWER WINDOW LEVER	Not Necessary	920.00 F	*- FL
13	1	*FRONT L/H POWER WINDOW SWITCH	Not Necessary	580.00 F	*- FL
14	1	*FRONT L/H DOOR PANEL INSULATOR FILM	Not Necessary	155.00 F	*- FL
15	1	*FRONT L/H DOOR PANEL INNER TRIM BOARD	Deformed/Torn	1,960.00 F	*1,021.00 FL
16	1	*FRONT L/H SPEAKER	Not Necessary	205.00 F	*- FL
17	1	*FRONT L/H LOWER CHROME MOULDING	Necessary	275.00 F	*186.00 FL
18	1	*FRONT L/H SIDE MIRROR FRAME	Cracked/Damaged	1,670.00 F	*1,201.40 FL
19	1	*FRONT L/H SIDE MIRROR LAMP UNIT	Not Necessary	235.00 F	*- FL
20	1	*FRONT L/H SIDE MIRROR GLASS	Not Necessary	1,350.00 F	*- FL
21	1	*FRONT L/H SIDE MIRROR COVER	Cracked	335.00 F	*145.00 FL
22	1	*FRONT L/H SIDE MIRROR SIGNAL LAMP	Not Necessary	290.00 F	*- FL
23	1	*FRONT L/H SIDE MIRROR SEALING	Not Necessary	55.00 F	*- FL
24	1	*REAR DOOR ASSY	Repair	2,450.00 F	*- FL
25	1	*REAR L/H LOWER CHROME MOULDING	Scratched	275.00 F	*185.00 FL
26	2	*REAR DOOR HINGE	Not Necessary	392.00 F	*- FL
27	4	*FRONT L/H DOOR HINGE SCREW	Not Necessary	60.00 FS	*- FS
28	3	*FRONT L/H DOOR MOUNTING CLIP	Not Necessary	27.00 FS	*- FS
29	3	*FRONT L/H SIDE MIRROR ANTENNA SCREW	Not Necessary	15.00 FS	*- FS
30	3	*FRONT L/H SIDE MIRROR FRAME SCREW	Not Necessary	30.00 FS	*- FS
31	4	*FRONT L/H SIDE MIRROR SIGNAL LAMP SCREW	Not Necessary	32.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 15,998.00 5,246.40
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 524.64

Total Parts (\$\$) 15,998.00 4,721.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR CHECKING ON WIRING	New	250.00	20.00
2	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS,INCLUDING WELDING,KNOCKING,REPAIRING,STRAIGHTENING,RESHAPE & ADJUSTMENT OF FRONT L/H DOOR ASSY & PARTS	New	2,800.00	500.00
3	SPRAYPAINTING & PUTTY OF FRONT L/H DOOR,SIDE MOULDING,FENDER,SIDE MIRROR,REAR L/H DOOR	New	2,400.00	750.00
4	LABOUR FOR RETROFITTING MOULDING & SEAL & DOOR MECHANISM	New	550.00	60.00
Gross Labour Cost (S\$)			6,000.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >