

TP Chinn Veron.
JTFH T02P800246676

1044-18425718

HP: 97236654

HENG KEE WORKSHOP

BLK 1033 FUNG AVE CAPOUT KIN GARDEN 40001
HP: 8156 2761

Specialties In: Accident Repair, Insurance Claims & Reporting, Service Repair, Paint Blending & Spray
Painting Of Automotive Vehicles

Q2474881

29.12.20

Dented 1855

~~# 2152.10~~

Rear	Bootlid	Striker	\$ 37.10	X	Not nec
Rear	Bootlid	Central Emblem	\$ 66.80	✓	Nec
Rear	Bootlid	Number Panel	\$ 177.10	X	Not Nec.
Rear	Bootlid	Rubber	\$ 368.90	X	Not Nec.
Rear	Bootlid	Inner Lock	\$ 249.60	✓	Damaged.
Rear	Bootlid	Auto Lock Top	\$ 489.50	X	Not Nec.
Rear	Taillamp		\$ 256.90	✓	cracked.
Rear	Taillamp	Lower Gurnish	\$ 84.60	✓	Dehd
Rear	Lower Gurnish	Bracket	\$ 33.40	X	Not nec.
Rear	Bumper		\$ 373.10	✓	Deformed.
Rear	Bumper	Clips	\$ 57.10	\$ 50	30 Nec.
Rear	Bumper	Lower Panel	\$ 323.90	X	Repair
Rear	Reverse	Sensor	\$ 280	200(sw)	Damaged.
To Wire			\$ 80	30	
To Under Costing			\$ 150	40	
To Windscreen			\$ 180	120	
To Spray Painting			\$ 850	650	
To Labour Charges			\$ 800	600	
To Reverse Sensor			labour charges	\$ 150	50.

List: 2916.
less 25%: 2187.

S.N: 200

Labour: 1490
total: 2187 + 200 + 1490
= 3877

L/S: 3.1K

04 Days.

3.1K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: