

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20014697/AVD3Q2

**Date:** 27/01/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00009112003
<b>Claimant Vehicle No :</b>	GZ4748E	<b>Insured Vehicle No :</b>	SLK5924B
Date of Loss:	23/12/2020	Nature of Claim:	TP
		Claim No:	SNM20D205151/C02/LEWLC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GZ4748E	Engine No:	1KD2833519
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	JTFHT02P800246676
Reg. Date:	04/03/2019 (Man. Year: 2018)	Odometer:	30177 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,895.00	2,387.00	2,508.00	51.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	1,490.00	720.00	32.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,105.00</b>	<b>3,877.00</b>	<b>3,228.00</b>	<b>45.43</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,105.00</b>	<b>3,100.00</b>	<b>4,005.00</b>	<b>56.37</b>

### INSPECTION

Date of Assignment:	29/12/2020	
Date Inspected:	30/12/2020 Inspected At:	Heng Kee Workshop (HQ) BLK 1033 EUNOS AVENUE 5A #01-31 Singapore 409703
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 26 Jan 2021)	
<b>Parts:</b>	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GZ4748E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	2,162.10 F	*1,855.00 FL
2	1		*REAR BOOTLID STRIKER	Not Necessary	39.10 F	*- FL
3	1		*REAR BOOTLID CENTAL EMBLEM	Necessary	66.80 F	*66.80 FL
4	1		*REAR BOOTLID NUMBER PANEL LAMP	Not Necessary	117.10 F	*- FL
5	1		*REAR BOOTLID RUBBER	Not Necessary	368.90 F	*- FL
6	1		*REAR BOOTLID INNER LOCK	Damaged	249.60 F	*249.60 FL
7	1		*REAR BOOTLID AUTO LOCK TOP	Not Necessary	489.50 F	*- FL
8	1		*REAR TAILLAMP	Cracked	256.90 F	*256.90 FL
9	1		*REAR TAILLAMP LOWER GARNISH	Deformed	84.60 F	*84.60 FL
10	1		*REAR LOWER GARNISH BRACKET	Not Necessary	33.40 F	*- FL
11	1		*REAR BUMPER	Deformed	373.10 F	*373.10 FL
12	10		*REAR BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
13	1		*REAR BUMPER LOWER PANEL	Repair	323.90 F	*- FL
14	1		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,895.00</b>	<b>3,116.00</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	0.00	729.00
<b>Total Parts (\$\$)</b>	<b>4,895.00</b>	<b>2,387.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REWIRE	New	80.00	30.00
2	TO UNDER COATING	New	150.00	40.00
3	TO SPRAY PAINTING	New	850.00	650.00
4	TO LABOUR CHARGES	New	800.00	600.00
5	TO REVERSE SENSOR LABOUR CHARGES	New	150.00	50.00
6	TO WINDSCREEN	New	180.00	120.00
<b>Gross Labour Cost (\$)</b>			<b>2,210.00</b>	<b>1,490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >