

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20014699/KEA3Q2  
**Date:** 16/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800003488
<b>Claimant Vehicle No :</b>	SJM4616K	<b>Insured Vehicle No :</b>	SLV2734U
Date of Loss:	23/12/2020	Nature of Claim:	TP
		Claim No:	0909611364SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJM4616K</b>	Engine No:	1AZE120113
Make & Model:	TOYOTA CAMRY, 2.0 ABS AIRBAG (A)	Chassis No:	MR053BK4107037248
Reg. Date:	05/01/2009 (Man. Year: 2008)	Odometer:	339607 km
Colour:	Metallic Pearl White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,341.27	1,648.27	3,693.00	69.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,475.00	375.00	20.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,191.27</b>	<b>3,123.27</b>	<b>4,068.00</b>	<b>56.57</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,500.00</b>		

## Adjuster Report

	(S\$)	7,191.27	2,500.00	4,691.27	65.24
<b>+ GST 7.00/7.00% (S\$)</b>		503.39	175.00	328.39	65.24
<b>Nett Amount (S\$)</b>		<b>7,694.66</b>	<b>2,675.00</b>	<b>5,019.66</b>	<b>65.24</b>
<b>+ Car Rental (7.0 x S\$150.00/day) (S\$)</b>			1,050.00		
	(S\$)		3,725.00		
<b>Liabile Amount (50.00%) (S\$)</b>			<b>1,862.50</b>		
<b>+ Doc/Search Fee (S\$)</b>			2.00		
<b>Nett Liability (S\$)</b>			<b>1,864.50</b>		
<b>Global Sum Settlement (S\$)</b>			<b>1,860.00</b>		

INSPECTION

Date of Assignment: 29/12/2020

Date Inspected: 20/01/2021

Inspected At:

S & H Motor Pte Ltd (Sin Ming)  
160 Sin Ming Drive #07-02, Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH REAR DOOR	Bent	1,248.00 FL	*1,248.00 FL
2	1		*RH REAR DOOR PROTECTOR	Necessary	91.70 FL	*91.70 FL
3	1		*RH REAR DOOR INNER LOCK	Repair	529.10 FL	*- FL
4	1		*RH REAR BUMPER RETAINER	Serviceable	79.40 FL	*- FL
5	1		*RH REAR WHEEL RIM 16	Dented / Cut	2,010.10 FL	*858.00 FL
6	1		*RH REAR KNUCKLE ARM	Serviceable	599.10 FL	*- FL
7	1		*RH REAR KNUCKLE ARM WHEEL BEARING	Not Necessary	611.70 FL	*- FL
8	1		*RH REAR LOWER ARM	Serviceable	420.60 FL	*- FL
9	1		*RH REAR CONTROL ARM	Serviceable	590.60 FL	*- FL
10	1		*RH REAR THRUST ARM	Serviceable	511.90 FL	*- FL
11	1		*RH REAR SHOCK ABSORBER	Serviceable	429.50 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>7,121.70</b>	<b>2,197.70</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	1,780.43	549.43
<b>Total Parts (S\$)</b>	<b>5,341.27</b>	<b>1,648.27</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND CHECK RH REAR SUSPENSION SYSTEM AND REPLACE DAMAGED PARTS	New	240.00	0.00
2	TO PERFORM COMPURISED WHEEL ALIGNMENT	New	65.00	60.00
3	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY	New	15.00	15.00
4	TO REMOVE DAMAGED PARTS ,TO JACK OUT RH REAR FENDER PANEL ,TO REWELD ,RESHAPE AND REPAIR RH REAR FENDER AND INNER PANEL,REAR BUMPER ,RH RUNNIGN BOARD GARNISH ,TO REMOVE AND REFIT RH REAR DOOR TRIM ,LOCK ,WINDOW AND ADJUST BODY PANEL ALIGNMENT	New	680.00	600.00
5	TO SPRAY PAINT AFFECTED RH REAR AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL	New	850.00	800.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,850.00</b>
				<b>1,475.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >