

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI20014700/QQD3E2**Date:** 10/05/2021**REFERENCE**

Insured/Claimant: QUEK CHEE YANG Policy No: DMPCSNW00156322000

Date of Loss: 21/12/2020

Nature of Claim: OD

Claim No: SNM20D205060/C01/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SKX5287A**

Make &amp; Model: MAZDA 3, 1.5 SEDAN L SP.6EAT (A)

Engine No: P520335296

Reg. Date: 17/12/2015 (Man. Year: 2015)

Chassis No: JM6BM42A8G0326926

Colour: Blue

Odometer: 147118 km

Engine Capacity: 1496 cc

Market Value/New Car Price: S\$50,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,255.00	2,795.00	-540.00	-23.95
Miscellaneous Items	25.00	25.00	0.00	0.00
Labour	323.40	281.40	42.00	12.99
Paintwork Labour	354.68	354.68	0.00	0.00
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,958.08</b>	<b>3,456.08</b>	<b>-498.00</b>	<b>-16.84</b>
<b>- Excess (S\$)</b>	500.00	0.00	500.00	100.00
<b>(S\$)</b>	2,458.08	3,456.08	-998.00	-40.60
<b>+ GST 7.00/7.00% (S\$)</b>	172.07	241.93	-69.86	-40.60
<b>Nett Amount (S\$)</b>	<b>2,630.15</b>	<b>3,698.01</b>	<b>-1,067.86</b>	<b>-40.60</b>

**INSPECTION**

Date of Assignment: 29/12/2020 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)

Date Inspected: 30/12/2020 Inspected At: Auto Insure Pte Ltd (HQ) (Woodlands)

6 Marsiling Lane  
Singapore 739145

Estimated Period of Repair: 5.0 days

**Adjuster:** OI SUN PIN**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2021)
Parts:	143	MAZDA 3 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX5287A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		2,255.00 F	*2,795.00 F
F=Franchise part.						
				Total Parts (\$\$)	2,255.00	2,795.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRA	25.00	25.00
Sub Total (\$\$)			25.00	25.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	LABOUR FOR SPRAY PAINT	New	354.68	354.68
<u>Labour Items</u>				
2	LABOUR FOR PANEL BEATING	New	323.40	281.40
Gross Labour Cost (\$\$)			678.08	636.08

Report was unsubmitted during this print-out.

< END OF ESTIMATES >