

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20014701/AGA3Q2

Date: 08/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993918

Claimant
Vehicle No : SJE4144Y **Insured Vehicle No :** SKM6914A

Date of Loss: 24/12/2020 Nature of Claim: TP Claim No: 3622155488SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJE4144Y		
Make & Model:	HONDA FIT, 1.3 G (A)	Engine No:	L13A4050568
Reg. Date:	24/04/2008 (Man. Year: 2008)	Chassis No:	GE61045743
Colour:	Blue	Odometer:	280493 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Goodride 6 mm	Rear Left Side:	Goodride 6 mm
Front Right Side:	Goodride 6 mm	Rear Right Side:	Goodride 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,178.90	3,625.92	13,552.98	78.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,130.00	2,630.00	4,500.00	63.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	24,308.90	6,255.92	18,052.98	74.26
Approved Total (Overridden) (\$\$)		5,000.00		
Nett Amount (\$\$)	24,308.90	5,000.00	19,308.90	79.43
+ Car Rental (7.0 x \$100.00/day) (\$\$)		700.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		5,707.45		

INSPECTION

Date of Assignment: 28/12/2020

Date Inspected: 28/12/2020 Inspected At:

Sm Automotive - Kaki Bukit (HQ)
BLOCK C - 1, KAKI BUKIT AVE 6,
#01-43
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	820.30 F	*820.30 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	97.80 F	*- FL
3	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	369.80 F	*- FL
4	1		*REAR BOOT LID EMBLEM LOGO	Necessary	38.10 F	*38.10 FL
5	1		*REAR BOOT LID FIT LOGO	Not Necessary	38.00 F	*- FL
6	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
7	1		*REAR BOOT LID CENTRE MOULDING	Not Necessary	120.60 F	*- FL
8	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	96.40 F	*- FL
9	6		*REAR BOOT LID CENTRE MOULDING CLIP	Not Necessary	39.00 F	*- FL
10	1		*REAR BOOT LID INNER LOCK	Jammed	232.10 F	*232.10 FL
11	1		*REAR BOOT LID INNER RUBBER	Cut	128.10 F	*128.10 FL
12	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	296.70 F	*296.70 FL
13	1		*REAR BOOT LID WIPER LINK	Not Necessary	175.90 F	*- FL
14	1		*REAR BOOT LID WIPER COVER	Not Necessary	45.00 F	*- FL
15	1		*REAR BOOT LID WIPER ARM	Not Necessary	86.00 F	*- FL
16	1		*REAR BOOT LID WIPER MOTOR	Not Necessary	328.50 F	*- FL
17	1		*REAR BOOT LID WINDSCREEN	Not Necessary	1,256.20 F	*- FL
18	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	136.20 F	*136.20 FL
19	2		*REAR TAIL LAMP	Cut	593.00 F	*593.00 FL
20	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*32.00 FL
21	2		*REAR TAIL LAMP PANEL	Repair	383.40 F	*- FL
22	2		*REAR TAIL LAMP INNER PANEL	Repair	964.60 F	*- FL
23	1		*REAR BUMPER	Distorted	494.60 F	*494.60 FL
24	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
25	2		*REAR BUMPER SIDE RETAINER	Necessary	57.40 F	*57.40 FL
26	1		*REAR BUMPER TOWING COVER	Deformed	28.00 F	*28.00 FL
27	2		*REAR BUMPER MUD SHIELD	Not Necessary	189.60 F	*- FL
28	8		*REAR BUMPER MUD SHIELD CLIP	Not Necessary	52.00 F	*- FL
29	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
30	1		*REAR END PANEL	Distorted	365.30 F	*365.30 FL
31	1		*REAR END PANEL TOP GARNISH	Deformed	140.20 F	*140.20 FL
32	2		*REAR FENDER	Repair	1,364.40 F	*- FL
33	2		*REAR FENDER GLASS	Not Necessary	576.00 F	*- FL
34	2		*REAR FENDER AIR DUCT	Not Necessary	76.00 F	*- FL
35	2		*REAR FENDER INNER PANEL	Repair	1,266.00 F	*- FL
36	2		*REAR FENDER INNER HOUSING	Repair	1,192.80 F	*- FL
37	2		*REAR FENDER TOP TRIM BOARD	Not Necessary	587.20 F	*- FL
38	2		*REAR FENDER INNER TRIM BOARD	N/S Deformed / O/S Cracked	679.60 F	*570.00 FL
39	1		*REAR FENDER INNER TRIM BOARD CLIP (16 PCS)	Necessary	104.00 F	*60.00 FL
40	1		*REAR SPARE TYRE PANEL	Repair	737.40 F	*- FL
41	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	260.40 F	*260.40 FL
42	1		*REAR SPARE TYRE PANEL TOP SPONGE	Not Necessary	206.00 F	*- FL
43	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	450.00 F	*- FL
44	2		*REAR SPARE TYRE SIDE PANEL	Repair	302.40 F	*- FL
45	1		*REAR EXHAUST	Not Necessary	586.50 F	*- FL
46	1		*REAR CENTRE EXHAUST	Not Necessary	562.40 F	*- FL
47	1		*REAR EXHAUST ALUMINIUM COVER	Not Necessary	95.00 F	*- FL
48	2		*REAR EXHAUST MOUNTING	Not Necessary	76.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Sub Total (\$)	17,178.90
					4,482.40	
					- List Item Discount on L Items 0.00/20.00% (\$)	0.00
						856.48
					Total Parts (\$)	17,178.90
						3,625.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	60.00
2	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
3	GUM	New	50.00	50.00
4	TO REMOVE & REFIT REAR LH & RH FENDER GLASS	New	200.00	0.00
5	GUM	New	100.00	60.00
6	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
7	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	0.00
8	TO REPAIR REAR CHASSIS MEMBER	New	480.00	0.00
9	TO CHECK WIRING	New	120.00	30.00
10	TOWING FEE	New	150.00	0.00
11	TUFF KOTE	New	150.00	60.00
12	PANEL BEATING	New	3,000.00	1,000.00
13	SPRAY PAINTING	New	2,000.00	1,200.00
Gross Labour Cost (\$)			7,130.00	2,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >