



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8741G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	I40VC COVER ASSY-RR BUMPE	TO REPAIR SEE LABOUR	1,106.00	-
10	I40VC BUMPER COVER CLIP R	NOT NECESSARY	22.00	-
1	I40VC COVER-RR BUMPER LWR	TO REPAIR SEE LABOUR	228.00	-
	LESS 20% DISCOUNT		-271.20	-
			1,084.80	-
<u>SPECIAL NETT ITEMS</u>				
1	HYUNDAI REVERSE SENSOR AS (SN)	SERVICEABLE	135.70	-
1	I40VC PROTECTOR MAT (METAL (SN)	BENT	50.00	50.00
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR FENDER ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
			435.70	300.00
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF I40VC COVER ASSY-RR BUMPE AND I40VC COVER-RR BUMPER LWR.		350.00	200.00
	SPRAYPAINT ON AFFECTED AREA.		250.00	200.00
	REMOVE / REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
			720.00	400.00
GRAND TOTAL			2,240.50	700.00
RECOMMENDED COST OF REPAIRS				700.00

Report Ref No. CS/SMO20014713/R1Utd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.