

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20014718/KGA3Q2
Date: 14/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070124958
Claimant Vehicle No :	SLH2524H	Insured Vehicle No :	SDA1318A
Date of Loss:	27/12/2020	Nature of Claim:	TP
		Claim No:	9309678625SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH2524H		
Make & Model:	TOYOTA AQUA, 1.5 E 1.5 SA (A)	Engine No:	1NZ8023089
Reg. Date:	27/10/2016 (Man. Year: 2016)	Chassis No:	NHP102568851
Colour:	White	Odometer:	88074 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	SUNWIDE 6 mm	Rear Left Side:	KAPSEN 4 mm
Front Right Side:	SUNWIDE 6 mm	Rear Right Side:	KAPSEN 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,049.47	1,132.47	917.00	44.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	570.00	510.00	47.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,129.47	1,702.47	1,427.00	45.60
Approved Total (Overridden) (S\$)		1,350.00		

(S\$)	3,129.47	1,350.00	1,779.47	56.86
+ GST 7.00/7.00% (S\$)	219.06	94.50	124.56	56.86
Nett Amount (S\$)	3,348.53	1,444.50	1,904.03	56.86
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
(S\$)		1,564.50		
Liable Amount (50.00%) (S\$)		782.25		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		784.25		

INSPECTION

Date of Assignment: 29/12/2020

Date Inspected: 29/12/2020

Estimated Period of Repair: 2.0 days

Inspected At: Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Adjuster: HOW MEI KWAN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	848.70 FL	*848.70 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Distorted	64.40 FL	*64.40 FL
3	1		*REAR BUMPER REINFORCEMENT	Repair	590.60 FL	*- FL
4	1		*REAR TAIL LAMP LH	Scratched	530.20 FL	*530.20 FL
5	1		*REAR FENDER AIR VENT LH	Serviceable	55.80 FL	*- FL
6	1		*REAR FENDER INNER LINER LH	Serviceable	129.60 FL	*- FL
7	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
8	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
9	1		*REAR BUMPER REVERSE SENSOR	Serviceable	300.00 FS	*- FS
10	1		*REAR FENDER INNER LINER CLIPS LH	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,604.30	1,493.30
- List Item Discount on L Items 25.00/25.00% (\$)	554.83	360.83
Total Parts (\$)	2,049.47	1,132.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX REPAIR & READJUST REAR ACCIDENT AREAS & ETC	New	400.00	200.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER ,REAR END PANEL & ETC	New	500.00	300.00
3	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
4	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC TO EFFECT REPLACE OF REAR BUMPER	New	100.00	50.00
Gross Labour Cost (S\$)			1,080.00	570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >