



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4450H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	IONIQVC COVER -RR BUMPER	CRACKED	459.40	459.40
1	BRACKET ASSY -RR BUMPER SI	NOT NECESSARY	55.80	-
22	I40VC BUMPER COVER CLIP R	NECESSARY	22.00	22.00
1	MOULDING ASSY -RR BUMPER C	CRACKED	451.25	451.25
	LESS 20% DISCOUNT		-197.69	-186.53
			790.76	746.12
	<u>NETT ITEMS</u>			
1	HYUNDAI REVERSE SENSOR AS (N)	CUT	180.00	180.00
	LESS 10% DISCOUNT		-18.00	-18.00
			162.00	162.00
	<u>LABOUR</u>			
	PANEL BEATING (REPAIR RR FENDER RH).		500.00	320.00
	SPRAYPAINT ON AFFECTED AREA.		450.00	400.00
	REMOVE/REFIX REVERSE SENSOR .		120.00	30.00
			1,070.00	750.00
	GRAND TOTAL		2,022.76	1,658.12
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,658.12

Report Ref No. NS/INC20014719/T1vd3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.