

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20014720/QQD3Q2

Date: 28/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070140386
Claimant
Vehicle No : SMU2475K **Insured Vehicle No :** SMV4879K
Date of Loss: 25/12/2020 Nature of Claim: TP Claim No: 6399049750SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU2475K**
Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B5573754
Reg. Date: 03/08/2020 (Man. Year: 2019) Chassis No: RU11323717
Colour: Grey Odometer: 6674 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,633.80	1,684.56	4,949.24	74.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	1,200.00	2,500.00	67.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,333.80	2,884.56	7,449.24	72.09
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	10,333.80	2,300.00	8,033.80	77.74

INSPECTION

Date of Assignment: 29/12/2020
Date Inspected: 04/01/2021 Inspected At: Xin Yun Auto Pte Ltd (kaki Bukit) (HQ)
8 Kaki Bukit Avenue 4, #05-23
Premier @ Kaki Bukit
Singapore 415875
Estimated Period of Repair: 4.0 days

Adjuster: OI SUN PIN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER ASSY	Crumpled	1,233.20 F	*845.00 FL
2	1		*BUMPER RIGHT BRACKET	Serviceable	95.00 F	*- FL
3	1		*BUMPER RETAINER	Broken	95.00 F	*95.00 FL
4	1		*BUMPER REINFORCEMENT	Serviceable	260.60 F	*- FL
5	1		*RR TAILLAMP	Scratched	805.90 F	*480.00 FL
6	1		*TAILLAMP LOWER BRACKET	Serviceable	97.50 F	*- FL
7	1		*FENDER	Repair	682.30 F	*- FL
8	1		*FENDER GARNISH	Scratched	88.20 F	*88.20 FL
9	1		*WHEEL COWLING	Repair	208.60 F	*- FL
10	1		*FRONT RIGHT WHEEL ARCHER	Serviceable	195.50 F	*- FL
11	1		*RR BUMPER SIDE/QUARTER PANEL	Crumpled	285.00 F	*285.00 FL
12	1		*ABSORBER LINK	Serviceable	267.00 F	*- FL
13	1		*ABSORBER BAR	Serviceable	185.50 F	*- FL
14	1		*BRAKE PEDAL	Serviceable	375.00 F	*- FL
15	1		*ABSORBER ASSY	Serviceable	450.00 F	*- FL
16	10		*BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
17	1		*FENDER INNER COWLING CLIPS (6 Pcs)	Necessary	40.00 FS	*20.00 FS
18	1		*QUARTER GLASS SEALANT	Serviceable	60.00 FS	*- FS
19	8		*SENSOR	Shorted	250.00 FS	*200.00 FS
20	1		*RIM	Serviceable	909.50 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,633.80	2,043.20
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	358.64
Total Parts (\$)	6,633.80	1,684.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS	New	1,500.00	400.00
2	TO PUTTY AND SPRAY PAINTING FRONT PORTION,FRONT BUMPER,SIDE FENDER,DOOR TOUCH UP,SIDE MIRROR,BONNET SIDE TOUCH UP	New	1,600.00	700.00
3	TO CHECK WIRING AND FOCUS TAILLAMP	New	60.00	30.00
4	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA	New	120.00	40.00
5	TO REMOVE AND CHECK UNDERCARRIAGE PARTS,AXEL NEED TO CHECK,AS THE ALIGNMENT RESULT SHOWS THE WRONG READING	New	180.00	0.00
6	TO BALANCE FRONT LEFT WHEEL	New	60.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	100.00	0.00
8	TO REMOVE AND INSTALL REAR BUMPER SENSOR	New	80.00	30.00
Gross Labour Cost (\$\$)			3,700.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >