



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 1558R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	N/S TAIL DOOR	BENT	1,550.00	1,550.00
1	N/S TAIL DOOR "PEUGEOT" EMBLEM	NECESSARY	65.00	65.00
1	O/S TAIL DOOR	BENT	1,350.00	1,350.00
1	O/S TAIL DOOR "PARTNER" EMBLEM	NECESSARY	85.00	85.00
1	REAR BUMPER	BENT	520.00	520.00
1	REAR BUMPER REINFORCEMENT	BENT	440.00	440.00
1	REAR END PANEL	BENT	340.00	340.00
	LESS 10% DISCOUNT		-435.00	-435.00
			3,915.00	3,915.00
1	TAIL DOOR RUBBER (50%)(SN)	DISTORTED	240.00	120.00
	LESS 10% DISCOUNT		-24.00	-
			216.00	120.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR W/S GLASS SEALANT (SN)	NECESSARY	60.00	60.00
1	TAIL DOOR 70KM/H STICKER (SN)	NECESSARY	15.00	15.00
1	TAIL DOOR 6 PAX STICKER (SN)	NECESSARY	15.00	15.00
			90.00	90.00
	<u>LABOUR</u>			
	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		240.00	160.00
	TO REMOVE ROOF LINING,FRONT AND REAR SEATS,TRIM BOARD AND CARPET.		60.00	60.00
	TO APPLY UNDERSEALING.		60.00	60.00
	TO PUTTY AND SPRAY REPLACED PARTS.		800.00	600.00
	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS.		700.00	600.00
			1,860.00	1,480.00
	GRAND TOTAL		6,081.00	5,605.00



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,450.00
---	--	--	----------

Report Ref No. CS/AGI20014721/Kvd3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.