

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20014723/KQD3E2

Date: 01/02/2021

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. Policy No: 0999993937

Date of Loss: 11/12/2020

Nature of Claim: OD

Claim No: 6557903244SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE7515K	Engine No:	10JBFR0023433
Make & Model:	PEUGEOT PARTNER, 1.6 HDI ETG LWB (A)	Chassis No:	VF37F9HF8FJ879163
Reg. Date:	23/03/2016 (Man. Year: 2015)	Odometer:	164342 km
Colour:	White		
Engine Capacity:	1560 cc		
Market Value/New Car Price:	S\$37,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Windforce 9 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Windforce 9 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,748.30	1,623.50	2,124.80	56.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	1,590.00	1,670.00	51.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,008.30	3,213.50	3,794.80	54.15
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	5,608.30	1,813.50	3,794.80	67.66
+ GST 7.00/7.00% (S\$)	392.58	126.95	265.63	67.66
Nett Amount (S\$)	6,000.88	1,940.45	4,060.43	67.66

INSPECTION

Date of Assignment: 30/12/2020

Date Inspected: 30/12/2020 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SLIDING DOOR-RH (WCP)	Bent	1,200.00 F	*1,200.00 F
2	1		*SLIDING DOOR PROTECTOR-RH (WCP)	Dented/Cut	185.00 F	*185.00 F
3	1		*SLIDING DOOR WEATHERSTRIP-RH (WCP)	Serviceable	178.00 F	*- F
4	1		*SLIDING DOOR CENTRE ROLLER-RH (WCP)	Serviceable	350.00 F	*- F
5	15		*SLIDING DOOR TRIMBOARD CLIPS-RH (WCP)	Necessary	132.00 FS	*30.00 FS
6	1		*REAR FENDER-RH (WCP)	Repair	1,200.00 F	*- F
7	15		*REAR FENDER TRIMBOARD CLIPS-RH (WCP)	Necessary	132.00 FS	*30.00 FS
8	1		*SLIDING DOOR GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
					Sub Total (\$\$)	3,437.00 1,485.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	311.30 138.50
					Total Parts (\$\$)	3,748.30 1,623.50

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT RH SLIDING DOOR GLASS	New	60.00	60.00
2	TO TRANSFER RH DAMAGED SLIDING DOOR INTERIOR MECHANISM TO NEW DOOR	New	120.00	60.00
3	TO PANEL BEAT AND STRAIGHTEN RH SLIDING DOOR PILLAR,RH REAR FENDER INNER PANEL,TO CUT AND WELD RH REAR FENDER,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY,TO REFIT AND ADJUST THE SAME	New	1,200.00	500.00
4	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
5	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	400.00
6	TO SUPPLY AND PASTE ARTWORK ON RH BODY PANEL	New	800.00	550.00
Gross Labour Cost (\$\$)			3,260.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >