LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20014725/R1TD3E2

Date: 11/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700023569

Claimant Vehicle Processes P

No: FBR6522C Insured Vehicle No: SLQ3049J

Date of Loss: 27/12/2020 Nature of Claim: TP Claim No: 1954246629SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBR6522C

Make & Model:YAMAHA FZ150, 150ccEngine No:HIDDENReg. Date:(Man. Year:)Chassis No:HIDDENColour:Multi-colourOdometer:0 km

Engine Capacity: 0 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/80-14 Rear Tyre Size: 130/70-13
Front Left Side: Federal 4 mm Rear Left Side: Federal 4 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 30/12/2020

Date Inspected:

M1 Motoring (HQ)
Inspected At:

411 Changi Road

Singapore 419860

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRONT FENDER WHEEL GUARD	Cracked	0.00 F	*-F
2	1	*FRONT HEADLAMP GARNISH RH	Scratched	0.00 F	*-F
3	1	*FRONT HEADLAMP RH	Scratched	0.00 F	*- F
4	2	*FRONT WING MIRROR	Scratched	0.00 F	*-F
5	1	*FRONT RH SIGNAL LAMP	Scratched	0.00 F	*- F
6	1	*HANDLE BAR BALANCER LH	Scratched	0.00 F	*-F
7	1	*HANDLE BAR BALANCER RH	Scratched	0.00 F	*- F
8	1	*CLUTCH LEVER	Scratched	0.00 F	*- F
9	1	*HAND BRAKE LEVER	Scratched	0.00 F	*- F
10	1	*INNER GARNISH FAIRING FRT	Cracked	0.00 F	*- F
11	1	*HANDLE-BAR GUIDE RH	Scratched	0.00 F	*- F
12	1	*HANDLE BAR GUIDE LH	Scratched	0.00 F	*- F
13	1	*CLUTCH ENGINE COVER	Scratched	0.00 F	*- F
14	1	*EXHAUST MUFFLER ASSY	Scratched	0.00 F	*-F
15	1	*FRT COWLING BRACKET	Cracked	0.00 F	*- F
16	1	*FRT COWLING	Scratched	0.00 F	*- F
F=Fra	anchise part.		Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >