

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG20014730/UQD3Q2

Date: 19/01/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29146062

Claimant
Vehicle No : SLU8425C

Insured Vehicle No : GBF5093T

Date of Loss: 29/12/2020

Nature of Claim: TP

Claim No: 632720

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU8425C**

Make & Model: TOYOTA C-HR HYBRID, 1.8 E G CVT (A)

Engine No: 2ZR8104091

Reg. Date: 15/12/2017 (Man. Year: 2017)

Chassis No: ZYX102038564

Colour: Black

Odometer: 300320 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18

Rear Tyre Size:

225/50 R18

Front Left Side: Michelin 7 mm

Rear Left Side:

Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side:

Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,927.90	3,776.32	21,151.58	84.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,470.00	1,860.00	2,610.00	58.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	29,397.90	5,636.32	23,761.58	80.83
Approved Total (Overridden) (\$)		4,500.00		
(\$)	29,397.90	4,500.00	24,897.90	84.69
+ GST 7.00/7.00% (\$)	2,057.85	315.00	1,742.85	84.69
Nett Amount (\$)	31,455.75	4,815.00	26,640.75	84.69

INSPECTION

Date of Assignment: 05/01/2021

Date Inspected: 30/12/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50

Autobay

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2021)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 E G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU8425C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,488.10 F	*- FL
2	1		*REAR WINDSCREEN MOULDING	Not Necessary	105.30 F	*- FL
3	1		*TAILGATE	Repair	1,650.00 F	*- FL
4	1		*TAILGATE OUTER GARNISH	Not Necessary	885.10 F	*- FL
5	1		*TAILGATE REAR LOGO	Not Necessary	68.60 F	*- FL
6	1		*TAILGATE TOYOTA EMBLEM	Not Necessary	60.20 F	*- FL
7	1		*TAILGATE C-HR EMBLEM	Not Necessary	68.10 F	*- FL
8	1		*TAILGATE HYBRID SYNERGY DRIVE LOGO	Not Necessary	85.00 F	*- FL
9	1		*TAILGATE INNER LOCK	Not Necessary	399.10 F	*- FL
10	1		*TAILGATE LOCK STRIKER	Not Necessary	105.00 F	*- FL
11	1		*TAILGATE INNER TRIM BOARD	Not Necessary	614.10 F	*- FL
12	1		*SET TAILGATE INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
13	1		*TAILGATE REFLECTORS	O/s Cracked	972.60 F	*395.10 FL
14	1		*TAILGATE WEATHERSTRIP	Not Necessary	399.20 F	*- FL
15	1		*REAR BUMPER	Deformed	1,451.10 F	*441.90 FL
16	1		*REAR BUMPER CENTRE PAD	Deformed	885.10 F	*456.10 FL
17	1		*REAR BUMPER TOW COVER	Not Necessary	45.00 F	*- FL
18	1		*REAR BUMPER SIDE RETAINERS	O/s Bent	130.00 F	*62.00 FL
19	1		*REAR BUMPER REFLECTORS	O/s Cracked	210.00 F	*65.00 FL
20	1		*REAR BUMPER REFLECTOR GARNISHS	O/s Scratched	330.00 F	*115.00 FL
21	1		*REAR BUMPER REINFORCEMENT	Bent	665.10 F	*322.70 FL
22	1		*REAR BUMPER LOWER CENTRE BRAKE LAMP	Not Necessary	350.00 F	*- FL
23	1		*REAR END PANEL	Dented	1,100.20 F	*716.00 FL
24	1		*REAR END PANEL TOP GARNISH	Not Necessary	485.10 F	*- FL
25	1		*REAR END PANEL LOCK SENSOR	Not Necessary	399.10 F	*- FL
26	1		*REAR FLOOR PANEL	Not Necessary	1,480.10 F	*- FL
27	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	811.10 F	*- FL
28	1		*REAR FLOOR PANEL TOOLS SPONGE	Not Necessary	688.90 F	*- FL
29	2		*REAR FENDERS	Not Necessary	1,982.00 F	*- FL
30	2		*REAR FENDER INNER TRIM BOARDS	Not Necessary	998.40 F	*- FL
31	1		*REAR FENDER OUTER PROTECTORS	O/s Cracked	430.40 F	*221.10 FL
32	1		*TAILLAMPS	O/s Cracked	1,511.60 F	*600.20 FL
33	2		*TAILLAMP HOUSING PANELS	Repair	532.20 F	*- FL
34	1		*REAR BLIND SPOT MONITOR O/S	Cracked	1,800.00 F	*1,580.00 FL
35	1		*REAR BLIND SPOT MONITOR BRACKET O/S	Bent	122.00 F	*60.00 FL
36	1		*REAR EXHAUST	Not Necessary	1,420.10 F	*- FL
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
38	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
39	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 24,927.90 5,035.10
- List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 1,258.78

Total Parts (\$\$) 24,927.90 3,776.32

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	120.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO REMOVE REPLACED,RECALIBRATE PROGRAM BLIND SPOT MONITOR	New	350.00	100.00
7	TO TRANSFER TAILGATE MECHANISM	New	100.00	0.00
8	TO SPRAY RUST PROOFING	New	120.00	30.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	680.00
10	TO PUTTY & SPRAY PAINTING	New	1,600.00	900.00
Gross Labour Cost (\$\$)			4,470.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >