

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI20014731/R1QD3E2
Date: 14/01/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00000772001
Claimant Vehicle No: GBE1285M Insured Vehicle No: SJM4941X
Date of Loss: 25/12/2020 Nature of Claim: TP Claim No: SNM20D205155/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE1285M
Make & Model: NISSAN NV200, 1.5 L ABS AIRBAG 2WD 6DR EURO 5 (M) Engine No: K9KC400D054767
Reg. Date: 09/09/2015 (Man. Year: 2015) Chassis No: VSKYBAM20Z0109665
Colour: Red Odometer: 221332 km
Engine Capacity: 1461 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R14 Rear Tyre Size: 185/65 R14
Front Left Side: Crucero 6 mm Rear Left Side: Crucero 6 mm
Front Right Side: Crucero 6 mm Rear Right Side: Crucero 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/12/2020
Date Inspected: 30/12/2020 Inspected At: Heng Motor Services Pte Ltd (HQ)
Estimated Period of Repair: 4.0 days Blk 5 #01-582 Defu Lane 10
Singapore 539186

Adjuster: MOHD RASUL **Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Jan 2021)	
Parts:	N/A	NISSAN NV200 1.5 L ABS AIRBAG 2WD 6DR EURO 5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE1285M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >