

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20014732/EVD3E2

Date: 08/02/2021

REFERENCE

Insured/Claimant: SENGMAN TJAJAJA Policy No: DMPCSNW00123422001

Date of Loss: 27/12/2020 Nature of Claim: OD Claim No: SNM20D205180/C01/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG1668B	Engine No:	DDBD001092
Make & Model:	BENTLEY CONTINENTAL, GT (A)	Chassis No:	SCBCA13S0JC070095
Reg. Date:	08/10/2018 (Man. Year: 2018)	Odometer:	4995 km
Colour:	Black		
Engine Capacity:	5950 cc		
Market Value/New Car Price:	S\$738,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/40ZR21	Rear Tyre Size:	265/40ZR21
Front Left Side:	Firelli 5 mm	Rear Left Side:	Firelli 5 mm
Front Right Side:	Firelli 5 mm	Rear Right Side:	Firelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	51,741.20	26,607.20	25,134.00	48.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,350.00	7,650.00	4,700.00	38.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	64,091.20	34,257.20	29,834.00	46.55
- Excess (S\$)	12,000.00	12,000.00	0.00	0.00
(S\$)	52,091.20	22,257.20	29,834.00	57.27
+ GST 7.00/7.00% (S\$)	3,646.38	1,558.00	2,088.38	57.27
Nett Amount (S\$)	55,737.58	23,815.20	31,922.38	57.27

INSPECTION

Date of Assignment: 30/12/2020

Date Inspected: 31/12/2020 Inspected At:

Wearnes automotive Pte Ltd (HQ)
45 LENG KEE ROAD
Singapore 159103

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$1,802.90 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2021)
Parts:	143	BENTLEY CONTINENTAL GT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG1668B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER PRIMED	Cut	7,189.80 FS	*7,189.80 FS
2	1		*BUMPER CARRIER	Not Necessary	2,507.00 FS	*- FS
3	1		*FOAM REINFORCEMENT F	Not Necessary	501.40 FS	*- FS
4	1		*GUIDE PROFILE	*Check	170.00 FS	*- FS
5	1		*GUIDE PROFILE	*Check	226.80 FS	*- FS
6	1		*GUIDE PROFILE	*Check	198.70 FS	*- FS
7	1		*GUIDE PROFILE	*Check	198.70 FS	*- FS
8	1		*GUIDE PROFILE	*Check	198.70 FS	*- FS
9	1		*GUIDE PROFILE	*Check	226.80 FS	*- FS
10	1		*GUIDE PROFILE	*Check	170.00 FS	*- FS
11	1		*BRACKET	*Check	206.60 FS	*- FS
12	1		*BRACKET	*Check	206.60 FS	*- FS
13	1		*AIR GUIDE GRILLE	Not Necessary	1,091.30 FS	*- FS
14	1		*WING LHF	Dented	17,022.40 FS	*17,022.40 FS
15	1		*BRACKET-FENDER	Bent	176.70 FS	*176.70 FS
16	1		*SUPPORT BRACKET	Not Necessary	796.40 FS	*- FS
17	1		*SUPPORT ELEMENT	Not Necessary	560.40 FS	*- FS
18	1		*B975804221C/BRACKET	Not Necessary	206.50 FS	*- FS
19	1		*BRACKET FOR DISTANCE	Necessary	82.40 FS	*82.40 FS
20	1		*B3SD807833/TRIM RING	Necessary	560.40 FS	*560.40 FS
21	1		*TRIM RING	Necessary	482.50 FS	*482.50 FS
22	1		*VENT GRILLE	Necessary	383.40 FS	*383.40 FS
23	1		*BRACKET-FENDER	Not Necessary	589.90 FS	*- FS
24	1		*BRACKET-FENDER	Not Necessary	73.70 FS	*- FS
25	1		*LED HEADLIGHT	Not Necessary	13,185.70 FS	*- FS
26	1		*TURN SIGNAL INDICATO	Not Necessary	3,376.90 FS	*- FS
27	1		*SENSOR PRIMED	Not Necessary	441.90 FS	*- FS
28	1		*ADHESIVE SEALER F12	Necessary	709.60 FS	*709.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	51,741.20	26,607.20
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT LH FENDER,FRT BUMPER,ETC	New	7,000.00	3,500.00
2	TO PUTTY SPRAY PAINT ON FRT BUMPER,FRT LH FENDER,ETC	New	3,600.00	2,400.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	1,750.00	1,750.00
Gross Labour Cost (\$\$)			12,350.00	7,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >