Adjuster Report Page 1 of 3

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20014734/KQD3Q2

**Date:** 27/01/2021

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001490047

Claimant
White No: SKL5977E Insured Vehicle No: SMQ153Z

Vehicle No: SNLD9//E Insured Venicle No: SIMQ 1532

Date of Loss: 29/12/2020 Nature of Claim: TP Claim No: 251469

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SKL5977E

Make & Model: LAND ROVER DISCOVERY 4, 3.0 DAB 4WD HID Engine No: 0748674306DT

TC SR EU4 (A)

Reg. Date: 29/11/2013 (Man. Year: 2013) Chassis No: SALLAAAG5DA691105

Colour: Metallic Dark Grey Odometer: 90731 km

Engine Capacity: 2993 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 255/55 R19 Rear Tyre Size: 255/55 R19
Front Left Side: Goodyear 9 mm Rear Left Side: Goodyear 9 mm
Front Right Side: Goodyear 9 mm
Rear Right Side: Goodyear 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,227.50	2,227.50	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	550.00	400.00	150.00	27.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	2,777.50	2,627.50	150.00	5.40

**INSPECTION** 

Date of Assignment: 30/12/2020

Date Inspected: 07/01/2021 Inspected At: Rc Auto-160 Sin Ming (HQ)

160 SIN MING DRIVE, #06-20 SIN

MING AUTOCITY Singapore 575722

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

# **REPAIR DETAILS**

Reference				
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jan 2021)		
Parts:	M1-SUV	LAND ROVER DISCOVERY 4 3.0 DAB 4WD HID TC SR EU4 (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	t Code: (Unsubmitted, no print-code for SKL5977E)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Cut	2,370.00 FL	*2,370.00 FL
2	1		*REAR BUMPER REFLECTOR	Missing	105.00 FL	*105.00 FL
F=Fra	anchise	part. L=ListIte	mDisc.	_		
				Sub Total (S\$)	2,475.00	2,475.00
			- List Item Discount on L Items	10.00/10.00% (S\$)	247.50	247.50
				Total Parts (S\$)	2,227.50	2,227.50

Adjuster Report Page 3 of 3

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	SPRAY PAINTING	New	250.00	200.00
2	TO RENEW ABOVE PARTS	New	300.00	200.00
		Gross Labour Cost (S\$)	550.00	400.00
	Donor			
	Repor	t was unsubmitted during this print-out.		

< END OF ESTIMATES >