

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:**

CC4/AIG20014750/GEA3Q2

**Date:**

13/08/2021

**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100339408

**Claimant Vehicle No :** SMK9428D**Insured Vehicle No :**

SKJ7734L

Date of Loss: 12/12/2020

Nature of Claim:

TP

Claim No:

0309540888SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMK9428D**

Make &amp; Model: ALFA ROMEO SPIDER, 2.0 (A)

Engine No: 1193555

Reg. Date: 29/04/2019 (Man. Year: 2019)

Chassis No: ZARPAHGN3K7C53599

Colour: Black

Odometer: 19435 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,337.00	2,894.00	1,443.00	33.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,980.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,317.00</b>	<b>4,874.00</b>	<b>1,443.00</b>	<b>22.84</b>
<b>+ GST 7.00/7.00% (S\$)</b>	442.19	341.18	101.01	22.84

<b>Nett Amount (S\$)</b>	<b>6,759.19</b>	<b>5,215.18</b>	<b>1,544.01</b>	<b>22.84</b>
<b>+ Car Rental (3.0 x S\$140.00/day + 7.00% GST) (S\$)</b>		449.40		
<b>+ Other Costs (S\$)</b>		1,321.45		
<b>Nett Liability (S\$)</b>		<b>6,986.03</b>		

INSPECTION

Date of Assignment: 29/12/2020

Date Inspected: 04/01/2021

Estimated Period of Repair: 3.0 days

Inspected At: EuroAutomobile Pte Ltd (HQ)  
24, LENG KEE ROAD #01-03  
SINGAPORE 159096

**Adjuster:** XING GUO QIANG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,490.00 F	*2,490.00 F
2	1		*SET FRONT BUMPER CLIP	Necessary	404.00 F	*404.00 F
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	113.00 F	*- F
4	1		*PAINT PROTECTION FILM -FRONT BUMPER PANEL	Not Necessary	1,300.00 FS	*- FS
5	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
					<b>Total Parts (\$\$)</b>	<b>4,337.00</b>
						<b>2,894.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R ONE FRONT BUMPER (NEW PART REPLACEMENT)	New	750.00	750.00
2	PAINTING ONE FRONT BUMPER PANEL	New	750.00	750.00
3	CALIBRATION OF ACC/SPEED SENSOR -ADD JOB AFTER REPLACEMNET OF FRONT BUMPER	New	480.00	480.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,980.00</b>	<b>1,980.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >