

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20014758/UGA3Q2
Date: 06/08/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_01
Claimant Vehicle No :	SMD8924G	Insured Vehicle No :	GBH622P
Date of Loss:	26/12/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0002869

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD8924G	Engine No:	4B11BR9116
Make & Model:	MITSUBISHI LANCER, 2.0 L MIVEC (A)	Chassis No:	JMYSTCY4A8U004758
Reg. Date:	06/11/2008 (Man. Year: 2008)	Odometer:	176364 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,652.40	4,168.93	7,483.47	64.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,450.00	1,840.00	3,610.00	66.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,102.40	6,008.93	11,093.47	64.86
Approved Total (Overridden) (S\$)		4,800.00		

Nett Amount (S\$)	17,102.40	4,800.00	12,302.40	71.93
+ Car Rental (8.0 x S\$120.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,767.45		

INSPECTION

Date of Assignment: 30/12/2020

Date Inspected: 30/12/2020

Estimated Period of Repair: 5.0 days

Inspected At:

1st Auto Pro Pte Ltd - 8 Kaki Bukit (HQ)
8 Kaki Bukit Avenue 4, #01-51/52 PREMIER @ KAKI BUKIT
Singapore 415875

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2021)
Parts: 143	mitsubishi LANCER 2.0 L MIVEC (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMD8924G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	793.00 FN	*755.00 FN
2	2		*REAR BOOT TAIL LIGHT LH/RH	Not Necessary	464.00 FN	*- FN
3	1		*REAR BOOT EMBLEM	Necessary	147.00 FN	*45.00 FN
4	1		*REAR BOOT LOGO LANCER	Necessary	152.00 FN	*47.20 FN
5	1		*REAR BOOT LOGO EX	Necessary	139.00 FN	*42.00 FN
6	1		*REAR BOOT LOGO GT	Necessary	145.00 FN	*45.00 FN
7	1		*REAR BOOT LOCK	Not Necessary	167.00 FN	*- FN
8	2		*REAR BOOT HINGE LH/RH	Not Necessary	368.00 FN	*- FN
9	1		*REAR BOOT INNER STOPPER	Not Necessary	115.00 FN	*- FN
10	2		*REAR BOOT ABSORBER LH /RH	Not Necessary	322.00 FN	*- FN
11	1		*REAR BOOT INNER RUBBER MOULDING	Not Necessary	266.00 FN	*- FN
12	1		*REAR BOOT INNER INSULATOR	Not Necessary	403.00 FN	*- FN
13	2		*REAR TAIL LAMP LH/RH	Not Necessary	1,108.00 FN	*- FN
14	1		*REAR END PANEL	Dented	606.00 FN	*445.00 FN
15	1		*REAR BUMPER REINFORCEMENT	Bent	385.00 FN	*220.00 FN
16	1		*REAR END PANEL TOP GARNISH	Twisted	249.00 FN	*168.00 FN
17	2		*REAR INNER TRIM BOARD LH/RH	Torn	446.00 FN	*442.00 FN
18	1		*REAR SPARE TYRE BOARD	Not Necessary	295.00 FN	*- FN
19	1		*REAR BOOT BRAKE LIGHT TOP CENTER	Cracked	336.00 FN	*250.00 FN
20	1		*REAR BUMPER	Torn	815.00 FN	*801.00 FN
21	2		*REAR BUMPER SIDE RETAINER LH/RH	Bent	230.00 FN	*64.00 FN
22	1		*REAR BUMPER TOWING COVER	Torn	120.00 FN	*28.00 FN
23	1		*REAR BUMPER REFLECTOR LH/RH	O/S Cracked	244.00 FN	*35.50 FN
24	1		*REAR SPARE TYRE TRUNK	Repair	521.00 FN	*- FN
25	1		*REAR BOOT INNER CLIP	Necessary	50.00 FS	*30.00 FS
26	1		*REAR BOOT SPOILER	Cracked	800.00 FS	*500.00 FS
27	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
28	1		*SET REAR NUMBER PLATE WITH HOLDER	Cracked	100.00 FS	*40.00 FS	
29	1		*SET REVERSE CAMERA	Shorted	300.00 FS	*300.00 FS	
30	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS	
31	1		*EXHAUST	Repair	2,200.00 FS	*- FS	
					Sub Total (\$)	12,536.00	4,507.70
					- Nett Item Discount on N Items 10.00/10.00% (\$)	883.60	338.77
					Total Parts (\$)	11,652.40	4,168.93

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT ELECTRICAL WIRING ,REPLACE DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING-REAR	New	200.00	30.00
2	TO REMOVE AND REFIT REAR EXHAUST TO FACILITATE THE REPAIR	New	300.00	60.00
3	TO REMOVE AND REFIT SPARE TYRE PANEL TO FACILITATE THE REPAIR }	New	150.00	80.00
4	TO REMOVE AND REFIT INNER TRIMS AND GARNISHES TO FACILITATE THE REPAIR }	New	250.00	0.00
5	TO REMOVE REPLACED AND TEST REVERSE SENSOR	New	200.00	50.00
6	TO TRANSFER BOOTLID COMPONENT FROM OLD TO NEW	New	200.00	60.00
7	PANEL BEATING ON AFFECTED AREA	New	2,000.00	600.00
8	SPRAY PAINTING	New	2,000.00	900.00
9	APPLY ANTI RUST ON AFFECTED AREA	New	150.00	60.00
			Gross Labour Cost (\$\$)	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >