

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014759/GTD3E2

Date: 03/02/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00093102000	
Claimant Vehicle No :	SKR8641Y	Insured Vehicle No :	SJK2544H	
Date of Loss:	27/12/2020	Nature of Claim:	TP	Claim No: SNM20D205183/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR8641Y		Engine No:	F2340983B38A15A
Make & Model:	BMW 218I, 1.5 ACTIVE TOURER D/AB LED DSC AB (A)		Chassis No:	WBA2A32070VZ50814
Reg. Date:	13/03/2015 (Man. Year: 2014)		Odometer:	77123 km
Colour:	White			
Engine Capacity:	1499 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,237.37	1,057.39	5,179.98	83.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	500.00	1,740.00	77.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,477.37	1,557.39	6,919.98	81.63
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	8,477.37	1,250.00	7,227.37	85.25
+ GST 7.00/7.00% (S\$)	593.42	87.50	505.92	85.25
Nett Amount (S\$)	9,070.79	1,337.50	7,733.29	85.25

INSPECTION

Date of Assignment:	30/12/2020		
Date Inspected:	11/01/2021	Inspected At:	Yong Sing Motor Works (HQ) 53 Defu Lane 12 Singapore 539144
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Feb 2021)

Parts: M1-MPV BMW 218I 1.5 ACTIVE TOURER D/AB LED DSC AB (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKR8641Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,255.40 F	*842.00 FL
2	10		*BUMPER CLIPS	Necessary	50.89 FS	*30.00 FS
3	1		*FRONT RETAINER BUMPER SIDE, LH	Not Necessary	107.30 F	*- FL
4	1		*FRONT RETAINER BUMPER SIDE, RH	Not Necessary	107.30 F	*- FL
5	1		*TOWING COVER FRONT	Not Necessary	117.80 F	*- FL
6	1		*FRONT GRILLE LH	Scratched	238.44 F	*86.05 FL
7	1		*FRONT GRILLE RH	Scratched	238.44 F	*86.05 FL
8	1		*FOG LAMP COVER RH	Not Necessary	221.32 F	*- FL
9	1		*FOG LAMP RH	Not Necessary	289.86 F	*- FL
10	1		*FRONT BUMPER CENTRE LOWER GRILLE	Not Necessary	329.67 F	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	546.12 F	*- FL
12	1		*FRONT BUMPER ABSORBER	Not Necessary	202.87 F	*- FL
13	1		*FRONT NUMBER PLATE W/FRAME }	Scratched	30.00 FS	*40.00 FS
14	1		*FRONT NUMBER PLATE BASE }	Scratched	180.13 FS	*- FS
15	1		*FRONT EMBLEM BMW	Necessary	180.13 F	*83.00 FL
16	1		*HEADLAMP FRONT RH	Not Necessary	2,141.70 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,237.37	1,167.10
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	109.71
Total Parts (\$\$)	6,237.37	1,057.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL ALL REPLACE ITEM, TO REPAIR FRONT PORTION	New	1,500.00	250.00
2	TO RESPRAY FRONT BUMPER	New	300.00	250.00
3	TO RESPRAY FRONT REINFORCEMENT	New	180.00	0.00
4	TO CHECK WIRING SYSTEM AND FUNCTION	New	100.00	0.00
5	TO REMOVE SUNDRY PARTS	New	100.00	0.00
6	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			2,240.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >