



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3156Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	I40VC COVER ASSY-RR BUMPE	DEFORMED	1,106.00	1,106.00
1	I40VC COVER-RR BUMPER LWR	SERVICEABLE	228.00	-
1	I40VC ABSORBER-RR BUMPER	SERVICEABLE	119.50	-
10	I40VC BUMPER COVER CLIP R	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-295.10	-225.60
			1,180.40	902.40
SPECIAL NETT ITEMS				
1	I40VC PROTECTOR MAT (SN)	TORN	50.00	50.00
			50.00	50.00
LABOUR				
	PANEL BEATING.		300.00	280.00
	SPRAYPAINT CHARGE.		200.00	200.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	60.00
	RENEW ADVERTISEMENT STICKER-BUMPER.		50.00	50.00
			630.00	590.00
GRAND TOTAL			1,860.40	1,542.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,250.00

Report Ref No. NS/INC20014773/R1qd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.