

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CC3/AIG20014785/AVD3Q2  
**Date:** 19/02/2021**REFERENCE**Insured/Claimant: KAREN TEO Policy No: 1700023569  
Date of Loss: 27/12/2020 Nature of Claim: OD Claim No: 1954246629SG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLQ3049J**  
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN038975  
Reg. Date: 04/07/2017 (Man. Year: 2017) Chassis No: WAUZZZF43HA164129  
Colour: Silver Odometer: 61133 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$98,000.00  
Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:**CONDITION OF TYRES**Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,120.00	0.00	6,120.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,552.00	2,292.00	12,260.00	84.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,672.00</b>	<b>2,292.00</b>	<b>18,380.00</b>	<b>88.91</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	20,072.00	1,692.00	18,380.00	91.57
<b>+ GST 7.00/7.00% (S\$)</b>	1,405.04	118.44	1,286.60	91.57
<b>Nett Amount (S\$)</b>	<b>21,477.04</b>	<b>1,810.44</b>	<b>19,666.60</b>	<b>91.57</b>

**INSPECTION**Date of Assignment: 31/12/2020  
Date Inspected: 30/12/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 5.0 days**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR FENDER-RH	Repair	2,644.00 FS	*- FS	
2	1		*REAR WINDSCREEN	Not Necessary	1,141.00 FS	*- FS	
3	1		*1/4 GLASS-RH	Not Necessary	609.00 FS	*- FS	
4	1		*PRIMER	Not Necessary	19.00 FS	*- FS	
5	1		*WHEEL HOUSING LINER-RH	Not Necessary	237.00 FS	*- FS	
6	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	90.00 FS	*- FS	
7	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS	
8	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS	
9	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS	
10	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS	
11	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS	
12	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS	
13	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS	
					<b>Total Parts (\$\$)</b>	<b>6,120.00</b>	<b>0.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
2	TO DISMANTLE REAR BUMPER. TO REPAIR RHS REAR DOOR. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,250.00	1,000.00
3	TO RESPRAY RHS REAR FENDER, RHS REAR DOOR, DOOR HANDLE, RHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL AND END PANELLING, TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	4,750.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	0.00
6	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	0.00
7	TO INSTALL SOLAR FILM FOR 1/4 GLASS AND REAR WINDSCREEN	New	400.00	0.00
8	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS AND REAR WINDSCREEN	New	200.00	0.00
9	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>14,552.00</b>	<b>2,292.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >