

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20014790/DEA3Q2

Date:

15/07/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100381081

Claimant Vehicle No : SKS6999Z**Insured Vehicle No :**

GBD2219D

Date of Loss: 26/12/2020

Nature of Claim:

TP

Claim No:

0710488749SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKS6999Z**

Make & Model: MERCEDES-BENZ CLA180, 1.6 (R18 BI) (A)

Engine No:

27091030568183

Reg. Date: 12/03/2015 (Man. Year: 2014)

Chassis No:

WDD1173422N171529

Colour: Grey

Odometer:

135595 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size:

225/40 R18

Front Left Side: Michelin 5 mm

Rear Left Side:

Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,217.37	18,259.51	11,957.86	39.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,830.00	2,450.00	3,380.00	57.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,047.37	20,709.51	15,337.86	42.55
Approved Total (Overridden) (S\$)		16,500.00		

(S\$)	36,047.37	16,500.00	19,547.37	54.23
+ GST 7.00/7.00% (S\$)	2,523.32	1,155.00	1,368.32	54.23
Nett Amount (S\$)	38,570.69	17,655.00	20,915.69	54.23
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		18,462.49		
Global Sum Settlement (S\$)		18,460.00		

INSPECTION

Date of Assignment: 30/12/2020

Date Inspected: 30/12/2020

Inspected At: Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
Singapore 408934

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,509.95 FL	*1,509.95 FL
2	1		*REAR BUMPER LOWER GARNISH	Cracked	563.50 FL	*563.50 FL
3	1		*REAR BUMPER LOWER TRIM	Bent	304.80 FL	*304.80 FL
4	2		*REAR BUMPER SIDE RETAINER	Serviceable	79.20 FL	*- FL
5	2		*REAR BUMPER SIDE BRACKET	Not Necessary	222.20 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Not Necessary	807.60 FL	*- FL
7	1		*REAR BUMPER INNER BRACKET	Not Necessary	121.20 FL	*- FL
8	1		*REAR BUMPER LOWER BRACKET	Not Necessary	103.50 FL	*- FL
9	1		*REAR BUMPER WIRE HARNESS	Not Necessary	249.60 FL	*- FL
10	2		*TAILLAMP	Not Necessary	2,160.00 FL	*- FL
11	2		*TAILLAMP SEAL	Not Necessary	74.40 FL	*- FL
12	4		*PDC SENSOR	Damaged	1,545.60 FL	*1,248.00 FL
13	1		*END PANEL	Not Necessary	1,353.60 FL	*- FL
14	1		*END PANEL TOP GARNISH	Not Necessary	322.80 FL	*- FL
15	1		*BOOTLID	Bent	2,512.80 FL	*1,875.00 FL
16	1		*BOOTLID LOCK	Serviceable	369.15 FL	*- FL
17	1		*BOOTLID PUSH BUTTOM	Not Necessary	144.00 FL	*- FL
18	1		*BOOTLID MERCEDES STAR LOGO	Necessary	64.80 FL	*64.80 FL
19	1		*BOOTLID EMBLEM CLA 180	Necessary	118.80 FL	*87.00 FL
20	1		*BOOTLID WEATHERSTRIP	Not Necessary	220.80 FL	*- FL
21	1		*FRONT BUMPER	Cracked	1,861.20 FL	*1,421.90 FL
22	2		*FRONT BUMPER RETAINER	Not Necessary	91.20 FL	*- FL
23	1		*FRONT BUMPER INNER GUIDE	Cracked	234.00 FL	*234.00 FL
24	1		*FRONT BUMPER REINFORCEMENT	Bent	445.20 FL	*445.20 FL
25	1		*FRONT BUMPER LOWER GRILLE	Serviceable	207.60 FL	*- FL
26	1		*FRONT BUMPER SPONGE	Torn	210.00 FL	*210.00 FL
27	4		*FRONT PDC SENSOR	Damaged	1,527.20 FL	*1,527.20 FL
28	1		*SENSOR WIRE HARNESS	Not Necessary	457.20 FL	*- FL
29	1		*FRONT NOZZLE	Not Necessary	241.50 FL	*- FL
30	1		*FRONT NOZZLE COVER	Not Necessary	82.80 FL	*- FL
31	2		*FRONT HEADLAMP	O/S Cracked / N/S Mtg Cracked	6,607.90 FL	*5,746.00 FL
32	2		*FRONT HEADLAMP BRACKET	Not Necessary	146.40 FL	*- FL
33	1		*FRONT GRILLE	Broken	871.70 FL	*692.00 FL
34	1		*FRONT GRILLE EMBLEM LOGO	Dislodged / Broken	174.80 FL	*174.80 FL
35	1		*FRONT GRILLE EMBLEM CHROME GARNISH	Cracked	219.65 FL	*219.65 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT SUPPORT PANEL	Broken	918.50 FL	*918.50 FL
37	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	251.30 FL	*- FL
38	1		*BONNET	Bent	1,961.90 FL	*1,565.00 FL
39	1		*BONNET LOCK	Serviceable	136.00 FL	*- FL
40	1		*BONNET LOCK CATCH	Serviceable	52.00 FL	*- FL
41	2		*BONNET HINGE	Not Necessary	186.60 FL	*- FL
42	1		*AIR CON CONDENSER	Punctured	1,389.60 FL	*1,091.00 FL
43	1		*FRONT RH HEADLAMP CONTROL UNIT	Serviceable	1,052.40 FL	*- FL
44	1		*FRONT RH HEADLAMP XENON CONTROL UNIT	Serviceable	480.40 FL	*- FL
45	1		*FRONT BUMPER REINFORCEMENT	Repeated	412.80 FL	*- FL
46	1		*FRONT BUMPER REINFORCEMENT BRACKET RH	Bent	195.60 FL	*195.60 FL
47	1		*REAR BUMPER CLIP	Necessary	30.00 FS	*20.00 FS
48	1		*END PANEL TOP GARNISH CLIP	Not Necessary	40.00 FS	*- FS
49	1		*FRONT BUMPER CLIP	Necessary	30.00 FS	*20.00 FS
50	1		*FRONT GRILLE CLIP	Necessary	40.00 FS	*20.00 FS
51	1		*FRONT NUMBER PLATE	Bent	60.00 FS	*35.00 FS
52	1		*FRONT NUMBER PLATE GARNISH	Deformed	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	33,543.75	20,268.90
- List Item Discount on L Items 10.00/10.00% (\$)	3,326.38	2,009.39
Total Parts (\$)	30,217.37	18,259.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE,REFIT REAR LINING ,TRIM AND GARNISH	New	150.00	120.00
3	REMOVE AND RENEW REAR SENSOR	New	150.00	40.00
4	REMOVE AND RENEW FRONT SENSOR	New	150.00	40.00
5	REMOVE AND RENEW REAR EXHAUST	New	200.00	0.00
6	TRANSFER PARTS ,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	60.00
7	TRANSFER PARTS ,ATTACHMENT FROM OLD BONNET TO NEW	New	200.00	0.00
8	PANEL BEATING ON AFFECTED AREAS	New	2,200.00	1,000.00
9	SPRAY PAINTING ON AFFECTED AREAS	New	2,200.00	1,000.00
10	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	40.00
11	REMOVE AND REFIT CONDENSER AND TOP UP GAS	New	200.00	120.00
Gross Labour Cost (S\$)			5,830.00	2,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >