

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20014796/UBA3Q2  
**Date:** 05/04/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100452995-04
<b>Claimant Vehicle No :</b>	SKU3881M	<b>Insured Vehicle No :</b>	SLB177X
Date of Loss:	30/12/2020	Nature of Claim:	TP
		Claim No:	0310482174SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKU3881M</b>	Engine No:	L15B3521244
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11021228
Reg. Date:	23/07/2015 (Man. Year: 2015)	Odometer:	89504 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,889.12	3,701.80	10,187.32	73.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,360.00	1,970.00	2,390.00	54.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,249.12</b>	<b>5,671.80</b>	<b>12,577.32</b>	<b>68.92</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>18,249.12</b>	<b>4,500.00</b>	<b>13,749.12</b>	<b>75.34</b>
	<b>+ Car Rental (6.0 x S\$110.00/day) (S\$)</b>	660.00		
	<b>+ Doc/Search Fee (S\$)</b>	36.45		
	<b>Nett Liability (S\$)</b>	<b>5,196.45</b>		
	<b>Global Sum Settlement (S\$)</b>	<b>4,900.00</b>		

### INSPECTION

Date of Assignment:	31/12/2020	Nineteen Autowerks Pte Ltd (HQ)
Date Inspected:	31/12/2020 Inspected At:	BLK 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE
Estimated Period of Repair:	5.0 days	Singapore 417808

---

**Adjuster:** MARCUS CHUA

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,620.00 FL	*953.00 FL
2	1		*TAILGATE LOGO	Not Necessary	82.00 FL	*- FL
3	1		*TAILGATE EMBLEM VEZEL	Necessary	86.20 FL	*56.20 FL
4	1		*TAILGATE OUTER GARNISH	Not Necessary	312.00 FL	*- FL
5	2		*TAILGATE REFLECTOR	Not Necessary	650.00 FL	*- FL
6	1		*TAILGATE WIPER MOTOR	Not Necessary	398.00 FL	*- FL
7	2		*TAILGATE WINDSCREEN MOULDING	Necessary	164.00 FL	*88.20 FL
8	1		*TAILGATE INNER LOCK	Twisted	287.00 FL	*109.20 FL
9	1		*TAILGATE LOCK SOLENOID SWITCH	Not Necessary	220.00 FL	*- FL
10	1		*TAILGATE LOCK STRIKER	Not Necessary	97.00 FL	*- FL
11	1		*TAILGATE TRIMBOARD	Deformed / Cracked	395.00 FL	*175.50 FL
12	1		*TAILGATE WEATHERSTRIP	Twisted	247.00 FL	*101.30 FL
13	1		*TAILLAMP	N/S Cracked	1,378.00 FL	*460.80 FL
14	1		*REAR BUMPER	Dented	985.00 FL	*549.20 FL
15	2		*REAR BUMPER SIDE RETAINER	Not Necessary	164.00 FL	*- FL
16	2		*REAR BUMPER SIDE GARNISH	Repair	632.00 FL	*- FL
17	2		*REAR BUMPER REFLECTOR	Not Necessary	234.00 FL	*- FL
18	1		*REAR BUMPER LOWER COVER	Deformed / Twisted	326.00 FL	*315.20 FL
19	1		*SMART BUZZER	Not Necessary	224.00 FL	*- FL
20	1		*REAR END PANEL	Dented / Buckled	785.00 FL	*514.00 FL
21	1		*REAR END PANEL TOP GARNISH	Twisted	274.00 FL	*188.00 FL
22	1		*SPARE TYRE PANEL	Repair	1,230.00 FL	*- FL
23	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	420.00 FL	*- FL
24	1		*SPARE TYRE PANEL TOOLS TRAY	Not fitted	264.00 FL	*- FL
25	1		*EXHAUST PIPE	Not Necessary	855.00 FL	*- FL
26	3		*EXHAUST MOUNTING	Not Necessary	169.20 FL	*- FL
27	2		*REAR FENDER ARCH GARNISH	Torn	430.00 FL	*360.40 FL
28	2		*REAR FENDER INNER SHIELD	Not Necessary	252.00 FL	*- FL
29	2		*REAR FENDER INNER GARNISH	Not Necessary	656.00 FL	*- FL
30	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
31	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	45.00 FS	*- FS
32	2		*SET TAILGATE REFLECTOR CLIPS	Not Necessary	50.00 FS	*- FS
33	2		*TAILGATE REFLECTOR SEAL	Not Necessary	40.00 FS	*- FS
34	1		*SET TAILGATE TRIMBOARD CLIPS	Necessary	55.00 FS	*40.00 FS
35	1		*TAILGATE WINDSCREEN PRIMER & CLEANER	Not Necessary	100.00 FS	*- FS
36	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*30.00 FS
37	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
38	1		*TAILGATE SEALANT	Not Necessary	100.00 FS	*- FS
39	2		*SET TAILLAMP CLIPS	Not Necessary	60.00 FS	*- FS
40	2		*TAILLAMP SEAL	Not Necessary	50.00 FS	*- FS
41	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*45.00 FS
42	1		*SET REAR BUMPER LOWER COVER CLIPS	Not Necessary	60.00 FS	*- FS
43	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
44	1		*SET REAR BUMPER TOP CHROME PLATE & PANEL TOP GARNISH	Bent	260.00 FS	*200.00 FS
45	1		*REAR BUMPER DEFUSER	Repair	380.00 FS	*- FS
46	2		*REAR BUMPER REFLECTOR CHROME GARNISH	Not Necessary	210.00 FS	*- FS
47	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
48	2		*SET REAR FENDER ARCH GARNISH	Not Necessary	90.00 FS	*- FS
49	2		*SET REAR FENDER INNER SHIELD	Not Necessary	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	2		*SET REAR FENDER INNER GARNISH	Not Necessary	100.00 FS	*- FS
51	1		*REVERSE CAMERA	Not Necessary	420.00 FS	*- FS
52	1		*SET REVERSE SENSOR WITH MODULE	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>16,656.40</b>	<b>4,476.00</b>
- List Item Discount on L Items 20.00/20.00% (\$)	2,767.28	774.20
<b>Total Parts (\$)</b>	<b>13,889.12</b>	<b>3,701.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING AND STRAIGHTEN PARTS ON ACCIDENT AREA	New	1,800.00	680.00
2	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT	New	80.00	20.00
3	R&R INTERIOR UPHOLSTERY	New	200.00	80.00
4	R&R TAILGATE COMPONENT	New	100.00	60.00
5	R&R TAILGATE WINDSCREEN	New	180.00	120.00
6	R&R EXHAUST PIPE	New	200.00	0.00
7	R&R REVERSE SENSOR AND CHECK	New	100.00	50.00
8	TO APPLY UNDERCOATING FOR RUST ROOFING	New	200.00	60.00
9	SPRAY PAINTING ON ACCIDENT AREA	New	1,500.00	900.00
<b>Gross Labour Cost (S\$)</b>			<b>4,360.00</b>	<b>1,970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >