3/30/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG20014804/T1GA3Q2

Date:

30/03/2021

REFERENCE

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800029185

Claimant Vehicle

GBD3464E

Insured Vehicle No:

GN5321J

No: Date of Loss:

17/12/2020

Nature of Claim:

TP

Claim No:

8498549672SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: Make & Model: **GBD3464E**

NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5

Engine No:

ZD30341495K

236848 km

Reg. Date:

(A)

12/09/2014 (Man. Year: 2014)

Chassis No: Odometer:

JN1SC2F24Z0856337

Colour: **Engine Capacity:** Silver

2953 cc

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Market Value/New Car Price:

Yes **Engine Modification:**

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

195 R15

Michelin 6 mm

Rear Tyre Size: Rear Left Side:

Rear Right Side:

165 R15 (D)

Maxxis 6/6 mm Maxxis 6/6 mm

Front Right Side: Michelin 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,308.09	2,758.37	8,549.72	75.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,080.00	1,450.00	3,630.00	71.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,388.09	4,208.37	12,179.72	74.32
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	16,388.09	3,350.00	13,038.09	79.56
+ GST 7.00/7.00% (S\$)	1,147.17	234.50	912.67	79.56
Nett Amount (S\$)	17,535.26	3,584.50	13,950.76	79.56
+ Car Rental (7.0 x S	\$60.00/day) (S\$)	420.00		
+ Doc/s	Search Fee (S\$)	7.45		
N	ett Liability (S\$)	4,011.95		

INSPECTION

Date Inspected:

Date of Assignment:

30/12/2020

12/01/2021 Inspected At:

Teamwork Garage Pte Ltd (HQ)

53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park

Singapore 408934

Estimated Period of Repair:

5.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printrpt&caseid=979653&extid=352564&CFID=83198147&C... 1/4

MOHD TAUFIKH BIN HAMID Adjuster: Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Bent	1,941.66 FL	*1,395.70 FL
2	3	*TAILGATE LOWER HINGE	Bent	138.00 FL	*138.00 FL
3	2	*TAILGATE STOPPER	Missing	29.28 FL	*29.28 FL
4	1	*TAILGATE SIDE HINGE LH	Not Necessary	183.60 FL	*- FL
5	1	*TAILGATE SIDE HINGE RH	Not Necessary	183.60 FL	*- FL
6	1	*TAILGATE LOCK CATCHER RH	Not Necessary	57.00 FL	*- FL
7	1	*TAILGATE LOCK CATCHER LH	Not Necessary	57.00 FL	*- FL
8	1	*FLOOR PANEL MEMBER	Repair	740.25 FL	*- FL
9	1	*TAILLAMP LH	Cracked	291.40 FL	*291.40 FL
10	1	*TAILLAMP RH	Cracked	291.40 FL	*291.40 FL
11	1	*TAILGATE PANEL RH	Bent	109.54 FL	*109.54 FL
12	1	*TAILGATE PANEL LH	Bent	109.54 FL	*109.54 FL
13	1	*SPARE TYRE TOP MEMBER	Repair	629.75 FL	*- FL
14	1	*REAR NUMBER PLATE LAMP	Not Necessary	64.00 FL	*- FL
15	1	*SIDE GATE LH	Repair	1,860.14 FL	*- FL
16	1	*REAR VIEW MIRROR	Not Necessary	489.50 FL	*- FL
17	1	*STEP GARNISH (AFTER MARKET)	Bent	450.00 FS	*280.00 FS
18	1	*STICKER -NISSAN	Necessary	70.00 FS	*70.00 FS
19	1	*STICKER -70KM/HR	Necessary	50.00 FS	*50.00 FS
20	1	*REAR NUMBER PLATE	Bent	80.00 FS	*30.00 FS
21	1	*SET REVERSE SENSOR	Cracked	400.00 FS	*200.00 FS
22	1	*ALUMINIUM TAILGATE BOARD	Not Necessary	1,000.00 FS	*- FS
23	1	*CANOPY	Not Necessary	2,800.00 FS	*- FS
F=Fra	nchise part. S=SpcNe	ett. L=ListItemDisc.			
			Sub Total (S\$)	12,025.66	2,994.86
		- List Item Discount	on L Items 10.00/10.00% (S\$)	717.57	236.49
			Total Parts (S\$)	11,308.09	2,758.37
		Report was unsubmitte	d during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labe	our Items			
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	80.00	30.00
2	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	30.00
3	TRANSFER PARTS ,ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	60.00
4	TRANSFER PARTS ,ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	0.00
5	REMOVE AND REPLACE ALUMINIUM TAILGATE BOARD	New	400.00	0.00
6	REMOVE AND REPLACE CANOPY TO FACILITATE REPAIR	New	500.00	0.00
7	PANEL BEATING ON AFFECTED AREAS	New	1,800.00	700.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	600.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
	Gross L	abour Cost (S\$)	5,080.00	1,450.00
	Report was unsubmitted during t	his print-out.		

< END OF ESTIMATES >