

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20014817/TGA3Q2**Date:** 08/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100465393
Claimant Vehicle No :	SFP2040R	Insured Vehicle No :	SLC4760E
Date of Loss:	27/12/2020	Nature of Claim:	TP
		Claim No:	6419241994SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFP2040R	Engine No:	4B11AX5466
Make & Model:	MITSUBISHI EVO-10, 2.0 GSR (M)	Chassis No:	CZ4A0000909
Reg. Date:	15/04/2008 (Man. Year: 2008)	Odometer:	45868 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/35 R18	Rear Tyre Size:	265/35 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	47,090.50	16,544.59	30,545.91	64.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,450.00	4,910.00	5,540.00	53.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	57,540.50	21,454.59	36,085.91	62.71
Approved Total (Overridden) (S\$)		17,150.00		
(S\$)	57,540.50	17,150.00	40,390.50	70.19
+ GST 7.00/7.00% (S\$)	4,027.84	1,200.50	2,827.34	70.19
Nett Amount (S\$)	61,568.34	18,350.50	43,217.84	70.19
+ Car Rental (10.0 x S\$150.00/day + 7.00% GST) (S\$)		1,605.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		19,962.95		
Global Sum Settlement (S\$)		19,900.00		

INSPECTION

Date of Assignment:	31/12/2020		
Date Inspected:	04/01/2021	Inspected At:	AP Automotive Services Pte Ltd (HQ) Blk 9006 Tampines Street 93, #01-202 Singapore 528840
Estimated Period of Repair:	10.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*HEADLAMP RH	Cracked	1,123.60 F	*1,016.00 FL
2	1	*FRONT BUMPER	Deformed	864.10 F	*864.10 FL
3	1	*FRONT BUMPER RETAINER RH	Deformed	31.50 F	*31.50 FL
4	1	*FRONT FENDER RH	Bent	951.40 F	*888.00 FL
5	1	*FRONT FENDER GARNISH RH	Deformed	97.80 F	*97.80 FL
6	1	*FRONT FENDER COWLING RH	Torn	117.10 F	*117.10 FL
7	1	*FRONT FENDER INNER PANEL RH	Repair	1,517.40 F	*- FL
8	1	*FRONT DOOR PILLAR RH	Bent	594.30 F	*394.00 FL
9	1	*FRONT DOOR RH	Bent	936.10 F	*936.10 FL
10	1	*FRONT DOOR SIDE MIRROR ASSY RH	Not Necessary	493.30 F	*- FL
11	1	*FRONT DOOR HANDLE RH	Not Necessary	79.10 F	*- FL
12	1	*FRONT DOOR WINDOW STICKER RH	Necessary	29.40 F	*29.40 FL
13	1	*FRONT DOOR WINDOW MOULDING WITH CHROME RH	Deformed	129.60 F	*129.60 FL
14	1	*FRONT DOOR INNER WINDOW MOULDING RH (NPA)	Not Necessary	0.00 F	*- FL
15	1	*FRONT DOOR LOCK RH	Bent	293.70 F	*293.70 FL
16	1	*FRONT DOOR LOCK CATCH RH	Bent	29.10 F	*29.10 FL
17	1	*FRONT DOOR INNER BOARD RH	Deformed	591.70 F	*591.70 FL
18	1	*FRONT DOOR WINDOW REGULATOR RH	Bent	151.30 F	*151.30 FL
19	1	*FRONT DOOR POWER WINDOW MOTOR RH	Jammed	437.10 F	*327.00 FL
20	2	*FRONT DOOR HINGE SET RH	Bent	74.80 F	*74.80 FL
21	1	*FRONT DOOR CHECKER RH	Bent	29.90 F	*29.90 FL
22	1	*FRONT DOOR WEATHERSTRIP RH	Necessary	134.30 F	*134.30 FL
23	1	*FRONT DOOR INNER WEATHERSTRIP RH	Cut	179.40 F	*179.40 FL
24	1	*FRONT DOOR INNER STEP GARNISH RH	Deformed	57.30 F	*57.30 FL
25	1	*DOOR CENTER PILLAR RH	Bent	499.20 F	*399.00 FL
26	1	*DOOR CENTER PILLAR INNER GARNISH TOP RH	Not Necessary	107.30 F	*- FL
27	1	*DOOR CENTER PILLAR INNER GARNISH LOWER RH	Not Necessary	136.40 F	*- FL
28	1	*REAR DOOR RH	Bent	859.30 F	*859.30 FL
29	1	*REAR DOOR WINDOW STICKER RH	Necessary	31.30 F	*31.30 FL
30	1	*REAR DOOR WINDOW MOULDING WITH CHROME RH	Necessary	137.40 F	*137.40 FL
31	1	*REAR DOOR INNER WINDOW MOULDING RH (NPA)	Not Necessary	0.00 F	*- FL
32	1	*REAR DOOR LOCK RH	Not Necessary	294.10 F	*- FL
33	1	*REAR DOOR LOCK CATCH RH	Not Necessary	29.40 F	*- FL
34	1	*REAR DOOR INNER BOARD RH	Deformed	596.40 F	*596.40 FL
35	1	*REAR DOOR WINDOW REGULATOR RH	Bent	151.40 F	*151.40 FL
36	1	*REAR DOOR POWER WINDOW MOTOR RH	Jammed	449.40 F	*325.00 FL
37	2	*REAR DOOR HINGE SET RH	Bent	80.60 F	*80.60 FL
38	1	*REAR DOOR CHECKER RH	Bent	31.40 F	*31.40 FL
39	1	*REAR DOOR WEATHERSTRIP RH	Necessary	139.70 F	*139.70 FL
40	1	*REAR DOOR INNER WEATHERSTRIP RH	Not Necessary	183.10 F	*- FL
41	1	*REAR DOOR INNER STEP GARNISH RH	Not Necessary	60.70 F	*- FL
42	1	*ROCKER PANEL RH	Repair	609.40 F	*- FL
43	1	*ROCKER PANEL OUTER GARNISH RH	Cracked	879.10 F	*679.00 FL
44	1	*REAR WINDSCREEN MOULDING	Necessary	43.70 F	*43.70 FL
45	1	*REAR FENDER RH	Distorted	873.10 F	*873.10 FL
46	1	*REAR FENDER INNER PANEL RH	Repair	461.40 F	*- FL
47	1	*REAR FENDER COWING RH	Deformed	109.10 F	*109.10 FL
48	1	*REAR BUMPER	Torn	732.90 F	*732.90 FL
49	1	*REAR BUMPER RETAINER RH	Damaged	21.70 F	*21.70 FL
50	1	*FRONT ABSORBER RH	Bent	719.40 F	*719.40 FL
51	1	*FRONT LOWER ARM RH	Bent	596.10 F	*544.00 FL
52	1	*FRONT KNUCKLE ARM RH	Bent	497.30 F	*443.00 FL
53	1	*FRONT KNUCKLE BEARING RH	Bent	419.70 F	*419.70 FL
54	1	*FRONT BEARING HUB RH	Not Necessary	401.40 F	*- FL
55	1	*FRONT DRIVE SHAFT RH	Not Necessary	1,173.10 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR ABSORBER RH	Bent	273.40 F	*273.40 FL
57	1		*REAR LOWER ARM RH	Bent	284.10 F	*284.10 FL
58	1		*REAR KNUCKLE RH	Bent	421.40 F	*421.40 FL
59	1		*REAR KNUCKLE BEARING RH	Bent	471.00 F	*378.00 FL
60	1		*REAR BEARING HUB RH	Serviceable	479.30 F	*- FL
61	1		*REAR AXLE	Not Necessary	1,204.10 F	*- FL
62	1		*FRONT DRIVER SEATBELT	Jammed	639.40 F	*439.00 FL
63	1		*HEADLAMP PROTECTIVE FILM	Not Necessary	600.00 FS	*- FS
64	1		*SET FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
65	1		*FRONT BUMPER LOWER CARBON FIBRE	Cracked	6,000.00 FS	*600.00 FS
66	1		*FRONT FENDER QUARTER GARNISH CARBON FIBRE	Deformed	800.00 FS	*100.00 FS
67	1		*FRONT DOOR PILLAR SEALANT	Not Necessary	200.00 FS	*- FS
68	1		*FRONT FENDER INNER PANEL SEALANT	Not Necessary	200.00 FS	*- FS
69	1		*FRONT FENDER SIGNAL LAMP	Not Necessary	500.00 FS	*- FS
70	1		*SET FRONT DOOR INNER BOARD CLIPS	Necessary	100.00 FS	*20.00 FS
71	1		*FRONT DOOR INNER ANTI SLIP MAT	Not Necessary	400.00 FS	*- FS
72	1		*DOOR CENTER PILLAR SEALANT	Necessary	200.00 FS	*50.00 FS
73	1		*SET REAR DOOR INNER BOARD CLIPS	Necessary	100.00 FS	*20.00 FS
74	1		*REAR DOOR PROTECTOR STICKER	Cut	300.00 FS	*100.00 FS
75	1		*REAR DOOR INNER ANTI SLIP MAT	Not Necessary	400.00 FS	*- FS
76	1		*ROCKER PANEL SEALANT	Not Necessary	250.00 FS	*- FS
77	1		*SET ROCKER PANEL OUTER GARNISH CLIPS	Necessary	100.00 FS	*30.00 FS
78	1		*SET ROCKER PANEL OUTER GARNISH PROTECTOR STICKER	Necessary	200.00 FS	*100.00 FS
79	1		*REAR WINDSCREEN SEALANT	Necessary	150.00 FS	*80.00 FS
80	1		*REAR FENDER SEALANT	Necessary	250.00 FS	*80.00 FS
81	1		*REAR FENDER INNER PANEL SEALANT	Not Necessary	250.00 FS	*- FS
82	1		*REAR FENDER PROTECTOR STICKER	Necessary	150.00 FS	*50.00 FS
83	1		*SET REAR FENDER COWLING CLIPS	Necessary	100.00 FS	*20.00 FS
84	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
85	1		*REAR BUMPER LOWER	Repair	2,000.00 FS	*- FS
86	1		*FRONT TYRE	Not Necessary	800.00 FS	*- FS
87	1		*FRONT RIM	Cut	4,000.00 FS	*500.00 FS
88	1		*REAR TYRE (70%) (\$400.00)	Torn	800.00 FS	*280.00 FS
89	1		*REAR RIM	Bent	4,000.00 FS	*500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	47,090.50	18,095.10
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,550.51
Total Parts (\$\$)	47,090.50	16,544.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON AFFECTED AREAS	New	2,800.00	2,000.00
2	PANEL BEATING ON AFFECTED AREAS	New	3,200.00	1,900.00
3	TO RNR REAR WINDSCREEN	New	400.00	120.00
4	TO RNR PROTECTOR STICKER	New	200.00	50.00
5	TO CHECK WIRING AND HEADLAMP FOCUS	New	150.00	30.00
6	TO RNR INNER TRIM AND UPHOLSTERY	New	800.00	100.00
7	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	80.00
8	TO RNR UNDERCARRIAGE	New	250.00	150.00
9	TO CHECK WHEEL BALANCING	New	250.00	60.00
10	TO CHECK WATER LEAK	New	150.00	50.00
11	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	150.00
12	TO PERFORM RUST PROOFING	New	600.00	100.00
13	TO RNR REAR AND FRONT DOOR MECHANISM	New	800.00	120.00
Gross Labour Cost (\$\$)			10,450.00	4,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >